



AF59UUM


report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	2009
Top speed	125 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-01
Pictures	34
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-22
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	19
Total items failed	17

MOT #18	2023-06-05 15:43
MOT test number	937043843193
Result	✓ Passed
Next expiry date	2024-06-22

MOT #17	2022-05-23 15:05
MOT test number	131694935519
Result	✓ Passed

MOT #16	2022-05-19 08:51
MOT test number	780162472458
Result	✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Nail in tyre
- Advice** Offside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2021-06-21 10:30**MOT test number** 702691388804**Result** ✓ Passed**MOT #14** 2020-06-23 12:05**MOT test number** 916041340235**Result** ✓ Passed**MOT #13** 2020-06-22 15:33**MOT test number** 375340327613**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #12 2019-07-24 08:34**MOT test number** 862966550120**Result** ✓ Passed**MOT #11** 2019-07-23 09:50**MOT test number** 450395998927**Result** ✗ Failed

- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #10 2018-07-18 15:20**MOT test number** 430324020011**Result** ✓ Passed

**MOT #9**

2018-07-18 10:34

MOT test number

260037846695

Result**✗ Failed**

- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Brake fluid contaminated (1.8 (a))
- Fail** Offside Rear Brake cable has restricted free movement (1.1.15 (e))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #8

2017-07-18 15:16

MOT test number

639147735540

Result**✓ Passed**

- Advice** Offside Front Tyre starting to wear on inner edge. 225/45-17.
- Advice** Scratches on windscreen.

MOT #7

2017-07-18 11:57

MOT test number

623108905985

Result**✗ Failed**

- Fail** Nearside Rear Mechanical brake component has restricted free movement Wheel won't rotate. (3.5.1k)
- Advice** Offside Front Tyre starting to wear on inner edge. 225/45-17.
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Scratches on windscreen.
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)



MOT #6	2016-07-19 16:34
MOT test number	489239626467
Result	✓ Passed
Advice	Engine cover fitted.
Advice	Items removed from driver's view prior to test
Advice	Under tray fitted.

MOT #5	2016-07-19 16:34
MOT test number	805070873158
Result	✗ Failed
Advice	Engine cover fitted.
Pass with rectification	Parking brake lever has no reserve travel (3.1.6b)
Advice	Under tray fitted.
Advice	Items removed from driver's view prior to test

MOT #4	2015-07-20 13:49
MOT test number	518741305279
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Notice	Both front tyres starting to wear on inner and outer edges.

MOT #3	2014-07-21 13:49
MOT test number	828502904295
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay



MOT #2	2013-07-23 12:40
MOT test number	398814203239
Result	✓ Passed

MOT #1	2012-07-23 11:40
MOT test number	215515102279
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
22 June 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-01
Last registration	2023-06-05
Complete history	See info



Registration #1	2009-09-01	27 mi
Registration #2	2012-07-23	58.150 mi
Registration #3	2013-07-23	63.574 mi
Registration #4	2014-07-21	68.447 mi
Registration #5	2015-07-20	73.445 mi
Registration #6	2016-07-19	79.441 mi
Registration #7	2016-07-19	79.441 mi
Registration #8	2017-07-18	85.590 mi
Registration #9	2017-07-18	85.592 mi
Registration #10	2018-07-18	90.896 mi
Registration #11	2019-06-20	95.377 mi
Registration #12	2019-06-20	95.377 mi
Registration #13	2019-06-20	95.377 mi
Registration #14	2019-06-20	95.377 mi
Registration #15	2019-06-20	95.377 mi
Registration #16	2019-06-20	95.377 mi
Registration #17	2019-06-20	95.377 mi
Registration #18	2019-06-20	95.377 mi
Registration #19	2019-06-20	95.377 mi
Registration #20	2019-06-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	090622085755BG