





report date: 2024-03-29

General information

Make	KIA
Model	PROCEED PRO CEED CRDI SE ECODYNAMICS
Colour	Black
Year of manufacture	2013
Top speed	122 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-07-09
Pictures	1
Listing price	<u>View report</u>



source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-07-14
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	20
Total items failed	2

MOT #13		2023-07-14 07:40
MOT test	number	849238318554
Result		✓ Passed
Next expi	ry date	2024-07-14
Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #12	2022-06-28 08:33
MOT test number	731596055483
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Front Tyre obviously under inflated (5.2.3 (I))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2021-07-15 11:03
MOT test number	726818191696
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

× Failed

MOT #10 2021-07-15 07:28

MOT test number 374120772568

Result

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MAJOR Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #9 2020-08-31 13:57

MOT test number 678710066357

Result
✓ Passed

MOT #8 2020-06-19 13:31

MOT test number 781139769766

Result
✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both nsr + osr (1.1.14 (a) (ii))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #7 2020-06-19 13:31

MOT test number 338758524465

Result × Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both nsr + osr (1.1.14 (a) (ii))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #6 2019-06-25 13:01

MOT test number 151131472571

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2019-06-25 09:41

MOT test number 435767321833

Result × Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm 2254517 (5.2.3 (e))

MAJOR Front Windscreen washer not working (3.5 (a))

MOT #4 2018-05-16 14:02

MOT test number 185878036877

Result \square Passed

MOT #3 2018-05-16 10:25

MOT test number 143877771823

Result ★ Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2 2017-05-02 10:38

MOT test number 242793772401

Result

Passed

MOT #1 2016-05-16 10:33

MOT test number 527359646243

Advice Advise n/s/f brake binding slightly.

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

,	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Correct registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-05-24
Last registration	2023-07-14
Complete history	See info



Registration #1	2013-05-24	26 mi
Registration #2	2016-05-16	29.364 mi
Registration #3	2017-05-02	34.162 mi
Registration #4	2018-05-16	41.855 mi
Registration #5	2018-05-16	41.855 mi
Registration #6	2019-06-25	57.542 mi
Registration #7	2019-06-25	57.542 mi
Registration #8	2020-06-19	71.537 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1430 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1490 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 page 1	2/12

Number of axles 2

Engine number D4FBDZ536582