





report date: 2024-03-29

General information

Make	PEUGEOT
Model	BOXER BLUE HDI 335 L3H2 PROFESSIONAL
Colour	White
Year of manufacture	2019
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 2

Date	2021-07-30


Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-07-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/10



MP19GUO report date: 2024-03-29

MOT history

MOT expiry date	2024-07-10
MOT pass rate	100 %
MOT passed	2
Failed MOT tests	0
Total advice items	5
Total items failed	0

MOT #2		2023-07-06 12:29
MOT test	number	230015860601
Result		✓ Passed
Next expi	ry date	2024-07-10
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Non obligatory mirror damaged	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

MOT #1	2022-06-30 15:24
MOT test number	412557855042
Result	✓ Passed

CarCheck.co.uk page 3/10



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

MP19GUO

report date: 2024-03-29

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2019-07-11
Last registration	2023-07-06
Complete history	See info



Registration #1	2019-07-11	29 mi
Registration #2		77,777 46
Registration #3		11.777 mi
Registration #4		71,777 es
Registration #5		D.777 66

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
60567	
60569	

Safety ratings

NCAP rating	***
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DY2Z4010303

CarCheck.co.uk page 10/10