





report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER BLUE HDI 335 L3H2 PROFESSIONAL
Colour	White
Year of manufacture	2017
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2025-04-22
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	28
Total items failed	3

MOT #7	2024-04-23 08:24
MOT test number	175630033741
Result	✓ Passed
Next expiry date	2025-04-22
Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Front Tyre slightly damaged/cracking or perishing Nearside & Offside (5.2.3	(d) (ii))
Advice Brake pedal wearing smooth (1.1.2 (c))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	
Advice Rear Tyre slightly damaged/cracking or perishing Nearside & Offside (5.2.3	(d) (ii))

CarCheck.co.uk page 2/11



LL67NRV

report date: 2024-03-28

MOT #6 2024-04-22 15:13

MOT test number 152988185274

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust emissions exceed level of metered smoke for a non-turbo charged engine (8.2.2.2 (b))

Advice Rear Tyre slightly damaged/cracking or perishing Nearside & Offside (5.2.3 (d) (ii))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Front Tyre slightly damaged/cracking or perishing Nearside & Offside (5.2.3 (d) (ii))

MOT #5 2024-04-22 14:17

MOT test number 481731874609

Result X Failed

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Front Tyre slightly damaged/cracking or perishing Nearside & Offside (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Rear Tyre slightly damaged/cracking or perishing Nearside & Offside (5.2.3 (d) (ii))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #4 2023-03-18 10:29

MOT test number 595524076841

Result \(\sqrt{Passed} \)

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Parking brake efficiency only just met. It would appear that the braking system requires

adjustment or repair. (1.4.2 (a) (i))

CarCheck.co.uk page 3/11



Result

LL67NRV

report date: 2024-03-28

✓ Passed

MOT #3 2022-03-28 11:16

MOT test number 327015030746

Result
✓ Passed

MOT #2 2021-04-02 11:25

MOT test number 997774444902

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Excessive hand brake travel

Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Front Lower chip in windscreen

Advice Nearside Front near side front damage repaired

MOT #1 2021-04-01 16:47

MOT test number 366058143444

Result X Failed

Advice Nearside Front near side front damage repaired

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Excessive hand brake travel

Advice Offside Front Lower chip in windscreen

Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



LL67NRV

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	

Plate changes	More info >
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-22
Last registration	2024-04-23
Complete history	See info



Registration #1	2017-11-22	22 mi
Registration #2	2021-04-01	68.988 mi
Registration #3	2021-04-02	68.988 mi
Registration #4	2022-03-28	83.245 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

page 10/11 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DYZZ4113898

CarCheck.co.uk page 11/11