





## General information

| Make                | RENAULT            |
|---------------------|--------------------|
| Model               | CLIO DYNAMIQUE NAV |
| Colour              | Black              |
| Year of manufacture | 2017               |
| Top speed           | 104 mph            |
| 0 - 60 mph          | 14.5 seconds       |
| Gearbox             | 5 speed Manual     |

## Engine & fuel consumption

| Power                   | 54 kW / 74 HP / 72 BHP |
|-------------------------|------------------------|
| Max. torque             | 107 Nm at 4.250 rpm    |
| Engine capacity         | 1.149 cc               |
| Cylinders               | 4                      |
| Fuel type               | Petrol                 |
| Consumption city        | 39.2 mpg               |
| Consumption extra urban | 60.1 mpg               |
| Consumption combined    | 50.4 mpg               |
| CO2 emission            | 127 g/km               |
| CO2 label               | D                      |





| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2021-02-04  |
| Pictures         | 1           |
| Listing price    | View report |



source: autoonline.co.uk



## MOT history

| MOT expiry date    | 2025-02-02 |
|--------------------|------------|
| MOT pass rate      | 71 %       |
| MOT passed         | 5          |
| Failed MOT tests   | 2          |
| Total advice items | 17         |
| Total items failed | 0          |

| MOT #7           | 2024-01-27 12:13 |
|------------------|------------------|
| MOT test number  | 286143906863     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-02-02       |

| MOT #6   |   | 2024-01-27 08:42 |
|----------|---|------------------|
| MOT test | number  | 789836310111     |
| Result   |   | 🗙 Failed         |
| MAJOR    | Service brake efficiency below requirements (1.2.2 (a) (i))                 |                  |
| MAJOR    | Offside Front Brake pipe excessively corroded (1.1.11 (c))                  |                  |
| MAJOR    | Offside Front Coil spring fractured or broken (5.3.1 (b) (i))               |                  |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))   |                  |
| MAJOR    | Offside Rear Brake pipe excessively corroded (1.1.11 (c))                   |                  |
| MAJOR    | Nearside Rear Service brake excessively binding (1.2.1 (f))                 |                  |
| Advice   | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |



**MD66VVP** report date: 2024-03-28

| MOT #5   |  | 2023-01-27 14:06 |
|----------|--|------------------|
| MOT test | number   | 343914994994     |
| Result   |  | Passed           |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #4   |   | 2023-01-27 08:26 |
|----------|---|------------------|
| MOT test | number  | 503004336633     |
| Result   |   | 🗙 Failed         |
| MAJOR    | Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) |                  |
| MAJOR    | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))              |                  |
| MAJOR    | Offside Rear Brake disc significantly and obviously worn $(1.1.14 (a) (i))$ |                  |

| MOT #3          | 2022-01-27 09:33 |
|-----------------|------------------|
| MOT test number | 854743715796     |
| Result          | ✓ Passed         |

| MOT #2                            | 2021-01-13 13:14 |
|-----------------------------------|------------------|
| MOT test number                   | 928184967428     |
| Result                            | ✓ Passed         |
| Advice Plastic under trays fitted |                  |





| MOT #1   |   | 2020-02-03 15:43 |
|----------|---|------------------|
| MOT test | number  | 806534847821     |
| Result   |   | ✓ Passed         |
| Advice   | Front brake discs slightly lipped             |                  |
| Advice   | Hand brake has little reserve travel          |                  |
| Advice   | Under trays fitted obscuring some components  |                  |
| Advice   | Nearside Rear bumper damaged (no sharp edges) |                  |



**MD66VVP** report date: 2024-03-28

# Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 February 2025 | ✓<br>MOT<br>Expires:<br>2 February 2025 |                                    |
|---|---|------------------------------------|
| Tax status<br>Days left                   |   | Valid until 1 February<br>279      |
| MOT expiry date<br>Full MOT history       |   | 2 February 2025<br>See MOT history |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |





#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |             |
|----------|-------------|
| Date     | FER I       |
| Category | <br>A PLANE |
| Туре     |             |
| Damage 2 | AMPLE       |
| Damage 2 | E Stand     |
| Date     | *           |
| Category | <br>ante.   |
| Туре     |             |

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 =      |

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| **********   |             |
| ********   |             |
| NUMBER OF TAXABLE   |             |
| **********   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this RENAULT had different number plates.   |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Carrent registration   |             |
| Plate since  |             |
|  | More info > |





#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 



mb66vvp report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 9          |
| First mileage registration | 2017-01-31 |
| Last registration          | 2024-01-27 |
| Complete history           | See info   |



| Registration #1 | 2017-01-31 | 11 mi      |
|-----------------|------------|------------|
| Registration #2 | 2020-02-03 | 15.955 mi  |
| Registration #3 | 2021-01-13 | 17.429 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 | 2022-01-27 | 24.428 mi  |
| Registration #6 |            | 11.777 est |
| Registration #7 |            | 11.777 mi  |
| Registration #8 |            | 11.777 esi |
| Registration #9 |            | 10.200 est |

More info >



# **MD66VVP** report date: 2024-03-28

## Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| S0482  |                  |
| \$0501 |                  |
| \$0566 |                  |
| \$0567 |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 88%             |
| Children       | 89%             |
| Pedestrian     | 66%             |
| Safety systems | 99%             |
| Overall rating | 85%             |
| Video          | see crash video |



| Dimensions & weight               |                       |
|-----------------------------------|-----------------------|
| Width                             | 1732 mm               |
| Height                            | 1448 mm               |
| Length                            | 4063 mm               |
| Wheel base                        | 2589 mm               |
| Kerb weight                       | 1059 kg               |
| Max. allowed weight               | 1564 kg               |
| Additional information            |                       |
| Fuel tank capacity                | 45                    |
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 12/12          |

| Number of axles | 2       |
|-----------------|---------|
| Engine number   | FB81433 |