

Ford



General information

FORD
RANGER WILDTRAK DCB 4X4
Black
2009
5 speed Manual

Engine & fuel consumption

Power	154 BHP	0 < 101 A
Max. torque	380 Nm	101 - 120 ^B _C
Engine capacity	2.953 cc	121 - 140 P
Cylinders	4	141 - 165 F
Fuel type	Diesel	166 - 185

225+



Internet history		
Entry 1		
Date	2021-06-14	
Pictures	8	
Listing price	View report	
FM, HQTORS	E196.61 wwww Frances ISHAMANG AWA Covid-19.5 ISHAMANG AWA Covid-19.5 ISHAMANG AWA Covid-19.5 ISHAMANG AWA Covid-19.5	
AWAITING PHOTOS	EXERCIT EL-HELDE EXERCITER EL-HELDE EXERCITER EL-HELDE EL-HELD	A restance of the second secon
01603.457249 sakes@fmmotorsnor		This dealer has signed our Dealer Promise

source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-15
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	18
Total items failed	3

MOT #14	2023-06-02 09:56
MOT test number	825466816985
Result	✓ Passed
Next expiry date	2024-06-15
Advice Nearside Front Headlamp (b))	has a product on the lens but not seriously reducing light output (4.1.4
Advice Offside Front windscreen w	washers weak
Advice Nearside Rear Wheel bear	ing has slight play (5.1.3 (a) (i))
Minor Offside Front Suspension ar	rm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice Offside Front Headlamp ha	as a product on the lens but not seriously reducing light output (4.1.4
Advice Offside Rear Wheel bearing	g has slight play (5.1.3 (a) (i))
Minor Nearside Front Suspension	arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))



MOT #13	2022-06-14 11:33
MOT test	number 839210096066
Result	✓ Passed
Advice (5.3.4 (a)	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2021-06-16 07:49
MOT test number	672953061708
Result	✓ Passed

MOT #11	2020-11-09 10:29
MOT test number	153172469444
Result	✓ Passed
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Offside Front Shock absorbers light misting of oil or has limited dampin	ng effect (5.3.2 (b))

MOT #10	2019-10-14 09:08
MOT test number	541617000512
Result	✓ Passed
MOT #9	2018-10-17 09:17
MOT test number	334449270772

✓ Passed





MOT #8	2017-11-02 16:59
MOT test number	341526007497
Result	✓ Passed
MOT #7	2017-11-02 16:25
MOT test number	242985153070
Result	🗙 Failed
Fail Offside Headlamp not working on main beam (1.7.5a)Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Fail Horn not working (1.6.2a)	

MOT #6		2016-10-11 15:37
MOT test i	number	923970437295
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	

MOT #5	2015-11-04 11:03
MOT test number	758562287967
Result	✓ Passed
MOT #4	2015-04-10 16:48
MOT test number	176090805109

Result

MOT #3	2014-04-09 10:16
MOT test number	775309294042
Result	✓ Passed

🗸 Passed





MOT #2	2013-04-23 09:23
MOT test number	507473413134
Result	✓ Passed
MOT #1	2012-04-13 14:44
MOT test number	359934102178
Result	✓ Passed



EKO9SWW report date: 2024-03-30

Tax & MOT check







Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second s	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



EKO9SWW report date: 2024-03-30

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-30
Last registration	2023-06-02
Complete history	See info



Registration #1	2009-04-30	13 mi
Registration #2	2012-04-13	35.859 mi
Registration #3	2013-04-23	52.178 mi
Registration #4	2014-04-09	64.258 mi
Registration #5	2015-04-10	74.540 mi
Registration #6	2015-11-04	75.214 mi
Registration #7	2016-10-11	92.379 mi
Registration #8	2017-11-02	105.042 mi
	2017 11 02	
Registration #9	1017 11 01	11.777 mi
-	10000 00 000 10000 00 00	11.227 est
Registration #9	1010 11 01 1010 25 29 1010 25 29	11.227 est 11.227 est 11.227 est
Registration #9 Registration #10	1010 11 01 1010 11 01 1010 10 10 1010 10 10	00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11	1000 00 000 1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 00	00.000 est 0.000 est 00.000 est 0.000 est 00.000 est
Registration #9Registration #10Registration #11Registration #12	1017 11 01 1017 11 01 1017 10 10 1017 10 10 1017 10 10 1017 10 10 1017 10 1017 10 1017 10 10 10 10 10 10 10 10 10 10 10 10 10 1	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9Registration #10Registration #11Registration #12Registration #13	1000 00 000 1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 00	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Additional informationFuel tank capacity70 lFuel deliveryDirect InjectionNumber of doors4Number of seats5Engine number143645