



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2014
Top speed	117 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-02-02
Pictures	48
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-11
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	43
Total items failed	12

MOT #14	2024-02-12 14:03
MOT test number	849268089156
Result	✓ Passed
Next expiry date	2025-02-11
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #13**

2024-02-07 16:52

**MOT test number**

591867539153

**Result****✗ Failed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear light unit damaged and has sharp edges
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Rear Reversing lamp inoperative (4.6.1 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MOT #12**

2023-02-10 15:45

**MOT test number**

615938797146

**Result**

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #11**

2023-02-10 14:40

**MOT test number**

386334967997

**Result**

✗ Failed

**Fail** Passenger's airbag obviously inoperative (7.1.5 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10**

2022-02-08 13:21

**MOT test number**

273880457138

**Result**

✓ Passed

**MOT #9** 2022-02-07 10:02**MOT test number** 261641209762**Result** ✗ Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Inner sidewall (5.2.3 (d) (i))

**MOT #8** 2021-10-23 09:22**MOT test number** 675757974739**Result** ✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

**MOT #7** 2020-11-07 16:23**MOT test number** 416706020073**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2020-11-07 16:23**MOT test number** 867199897079**Result** ✗ Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2019-11-02 12:11**MOT test number** 133860322996**Result** ✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #4** 2018-11-09 11:14**MOT test number** 100647965215**Result** ✓ Passed**MOT #3** 2018-11-05 12:12**MOT test number** 775294376691**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #2** 2018-03-09 09:19**MOT test number** 926535498580**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Vehicle fitted with covers and /or undertrays, unable to full inspect some parts of vehicle ;**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** MIL indicates engine fault**MOT #1** 2017-03-03 09:39**MOT test number** 367804302595**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
11 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	11 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 NL14GDK
Plate since	2019-03-28
Current registration	 NL14GDK
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-03-13
Last registration	2024-02-12
Complete history	<a href="#">See info</a>



Registration #1	2014-03-13	6 mi
Registration #2	2017-03-03	28.052 mi
Registration #3	2018-03-09	36.581 mi
Registration #4	2018-11-05	42.105 mi
Registration #5	2018-11-09	42.105 mi
Registration #6	2019-11-02	48.187 mi
Registration #7	2020-11-07	52.015 mi
Registration #8	2020-11-07	52.015 mi
Registration #9	2020-11-07	52.015 mi
Registration #10	2020-11-07	52.015 mi
Registration #11	2020-11-07	52.015 mi
Registration #12	2020-11-07	52.015 mi
Registration #13	2020-11-07	52.015 mi
Registration #14	2020-11-07	52.015 mi
Registration #15	2020-11-07	52.015 mi
Registration #16	2020-11-07	52.015 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 294843K LNQ