



HYUNDAI

VN63X0J

report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 CLASSIC
Colour	Red
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-07
Pictures	39
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-19
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	18
Total items failed	7

MOT #12	2023-07-20 12:00
MOT test number	749222879853
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Chip to windscreen
Advice	Rear Inner Brake pad(s) wearing thin nearside & offside (1.1.13 (a) (ii))

MOT #11	2022-07-14 10:35
MOT test number	803806546480
Result	✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated Upper dust cover (5.3.4 (b) (i))
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))

**MOT #10**

2022-07-05 12:53

MOT test number

354307879176

Result

✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure on the outer sidewall (5.2.3 (d) (ii))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated Upper dust cover (5.3.4 (b) (i))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Offside Side repeater slightly discoloured (4.4.3 (a))**MOT #9**

2021-07-19 18:00

MOT test number

994527300324

Result

✓ Passed

MOT #8

2021-07-19 14:55

MOT test number

446585283539

Result

✗ Failed

Fail Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**MOT #7**

2020-11-13 15:58

MOT test number

778251497402

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 185/60r15 (5.2.3 (e))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #6** 2020-11-13 15:58**MOT test number** 786403959069**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 185/60r15 (5.2.3 (e))**MOT #5** 2019-11-16 11:08**MOT test number** 725067091586**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 185/60r15 (5.2.3 (d) (ii))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #4** 2018-11-22 16:48**MOT test number** 638976785836**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-11-15 13:10**MOT test number** 977942474377**Result** ✓ Passed**MOT #2** 2016-12-02 11:46**MOT test number** 487837698277**Result** ✓ Passed



MOT #1	2016-12-02 11:46
MOT test number	419552443892
Result	✗ Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	VN63XOJ
Plate since	2019-09-29
Current registration	VN63XOJ
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-12-20
Last registration	2023-07-20
Complete history	See info



Registration #1	2013-12-20	21 mi
Registration #2	2016-12-02	8.476 mi
Registration #3	2016-12-02	8.476 mi
Registration #4	2017-11-15	14.118 mi
Registration #5	2018-11-22	18.718 mi
Registration #6	2019-11-16	22.742 mi
Registration #7	2020-11-13	27.854 mi
Registration #8	2020-11-13	27.854 mi
Registration #9	2020-11-13	27.854 mi
Registration #10	2020-11-13	27.854 mi
Registration #11	2020-11-13	27.854 mi
Registration #12	2020-11-13	27.854 mi
Registration #13	2020-11-13	27.854 mi
Registration #14	2020-11-13	27.854 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	G4LACM940592
---------------	--------------