



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	PREVIA D-4D T3 7STR
Colour	Blue
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 3.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.2 mpg
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 1	
Date	2021-11-24
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-25
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	69
Total items failed	16

MOT #23 2023-11-23 10:50

MOT test number 264026047661

Result ✓ Passed

Next expiry date 2024-11-25

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Axle bush (5.3.4 (a) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Axle bush (5.3.4 (a) (i))

MOT #22 2022-11-03 14:45

MOT test number 730677257969

Result ✓ Passed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Axle bush (5.3.4 (a) (i))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Axle bush (5.3.4 (a) (i))

MOT #21 2021-11-26 09:19

MOT test number 195865649649

Result ✓ Passed

**MOT #20**

2021-05-19 08:23

**MOT test number**

852403087986

**Result**

✓ Passed

**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #19**

2021-05-19 08:23

**MOT test number**

411810144639

**Result**

✗ Failed

**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #18**

2020-05-20 08:21

**MOT test number**

918695125987

**Result**

✓ Passed

**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17**

2019-05-20 09:42

**MOT test number**

571650998750

**Result**

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2019-05-20 09:42

**MOT test number**

360862026917

**Result**

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2018-05-25 13:33

**MOT test number**

920554797903

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2018-05-21 08:20

**MOT test number**

131463861717

**Result**

✗ Failed

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13**

2017-05-15 14:25

**MOT test number**

686872581458

**Result**

✓ Passed

- Advice** Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Central Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #12** 2016-05-20 14:04**MOT test number** 935049640624**Result** ✓ Passed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Rear tyre perished**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Rear Tyre worn close to the legal limit perished (4.1.E.1)**MOT #11** 2015-05-26 15:10**MOT test number** 238816945103**Result** ✓ Passed**Notice** Nsr tyre perished**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #10** 2015-05-26 15:10**MOT test number** 289016345198**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Nsr tyre perished**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #9** 2014-05-28 18:18**MOT test number** 838588544182**Result** ✓ Passed**Notice** Both rear axle bushes worn**MOT #8** 2014-05-27 16:20**MOT test number** 476597744180**Result** ✗ Failed**Notice** Both front tyres wearing on edges**Notice** Both rear axle bushes worn**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Centre brake light not working**Notice** Aux drive belts worn**Fail** Rear registration plate delaminated (6.3.1d)**Fail** Offside Front front brake excessively fluctuating (3.7.B.3)**MOT #7** 2013-05-22 16:43**MOT test number** 168562443137**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



**MOT #6** 2013-05-22 13:17**MOT test number** 508982043117**Result** ✗ Failed

**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Centre Rear Passenger's seat insecure (6.2.A.1)

**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2012-05-28 14:38**MOT test number** 987639342148**Result** ✓ Passed**MOT #4** 2011-05-16 14:53**MOT test number** 109486631116**Result** ✓ Passed

**Notice** Front pads worn

**Notice** Nail in offside front tyre

**Notice** Front discs worn

**Notice** Sidewall damage nearside front tyre

**MOT #3** 2010-06-03 17:47**MOT test number** 822854750100**Result** ✓ Passed

**Notice** Sidewall damage n/s front tyre

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Nail in offside front tyre

**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2 2010-06-03 17:00

MOT test number 294534650181

Result		✗ Failed
Fail	Front registration plate letter/figure incomplete (6.3.1c)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Sidewall damage n/s front tyre	
Fail	Front registration plate deteriorated (6.3.1d)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Nail in offside front tyre	

MOT #1 2009-06-03 15:20

MOT test number 940334059113

Result		✓ Passed
--------	--	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
25 November 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	25 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	WV06KPG
Plate since	2019-03-29
Current registration	WV06KPG
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-03-01
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2006-03-01	25 mi
Registration #2	2009-06-03	34.165 mi
Registration #3	2010-06-03	42.581 mi
Registration #4	2010-06-03	42.581 mi
Registration #5	2011-05-16	48.578 mi
Registration #6	2012-05-28	57.039 mi
Registration #7	2013-05-22	64.498 mi
Registration #8	2013-05-22	64.498 mi
Registration #9	2014-05-27	70.057 mi
Registration #10	2014-05-28	70.057 mi
Registration #11	2015-05-26	75.662 mi
Registration #12	2016-05-20	79.000 mi
Registration #13	2016-05-20	79.000 mi
Registration #14	2016-05-20	79.000 mi
Registration #15	2016-05-20	79.000 mi
Registration #16	2016-05-20	79.000 mi
Registration #17	2016-05-20	79.000 mi
Registration #18	2016-05-20	79.000 mi
Registration #19	2016-05-20	79.000 mi
Registration #20	2016-05-20	79.000 mi
Registration #21	2016-05-20	79.000 mi
Registration #22	2016-05-20	79.000 mi
Registration #23	2016-05-20	79.000 mi
Registration #24	2016-05-20	79.000 mi

More info >





Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1800 mm
Height	1845 mm
Length	4750 mm
Wheel base	2900 mm
Kerb weight	1740 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	1CD0544307
---------------	------------