



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D3 SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-04
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #14 2024-02-26 10:44

MOT test number 777162107581

Result ✓ Passed

Next expiry date 2025-03-04

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13 2023-02-24 09:32

MOT test number 953832709301

Result ✓ Passed**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2022-02-21 15:20

MOT test number 456428880568

Result ✓ Passed**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #11** 2022-02-21 10:16**MOT test number** 823597714554**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-03-05 13:33**MOT test number** 855143596576**Result** ✓ Passed**MOT #9** 2021-03-04 13:36**MOT test number** 532139477894**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Front Headlamp levelling device inoperative (4.1.5 (a))**MOT #8** 2020-06-15 13:39**MOT test number** 917371677880**Result** ✓ Passed**MOT #7** 2019-06-05 11:33**MOT test number** 811256009480**Result** ✓ Passed

**MOT #6** 2019-05-30 15:54**MOT test number** 340497290026**Result** ✗ Failed**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #5** 2018-05-22 13:35**MOT test number** 333055461651**Result** ✓ Passed**MOT #4** 2017-05-13 09:55**MOT test number** 718776195766**Result** ✓ Passed**MOT #3** 2016-05-23 09:37**MOT test number** 188172587591**Result** ✓ Passed**MOT #2** 2015-04-07 12:52**MOT test number** 999417395042**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**MOT #1** 2014-04-08 09:44**MOT test number** 548858894069**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BD11YKH
Plate since	2019-03-29
Current registration	BD11YKH
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-05-12
Last registration	2024-02-26
Complete history	See info



Registration #1	2011-05-12	20 mi
Registration #2	2014-04-08	44.392 mi
Registration #3	2015-04-07	50.469 mi
Registration #4	2016-05-23	59.007 mi
Registration #5	2017-05-13	68.058 mi
Registration #6	2018-05-22	76.214 mi
Registration #7	2019-05-30	84.322 mi
Registration #8	2019-06-05	84.386 mi
Registration #9	2019-06-05	84.386 mi
Registration #10	2019-06-05	84.386 mi
Registration #11	2019-06-05	84.386 mi
Registration #12	2019-06-05	84.386 mi
Registration #13	2019-06-05	84.386 mi
Registration #14	2019-06-05	84.386 mi
Registration #15	2019-06-05	84.386 mi
Registration #16	2019-06-05	84.386 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1026084
---------------	---------