



report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-07
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #16	2024-02-08 15:01
---------	------------------

MOT test number	949970617952
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-07
------------------	------------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear back box casing damaged

**MOT #15**

2024-02-08 14:43

MOT test number

878600649729

Result**✗ Failed****Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice

Nearside Rear back box casing damaged

Advice

Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #14

2023-01-28 14:46

MOT test number

399414459600

Result**✓ Passed****Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13

2023-01-28 14:46

MOT test number

536640026372

Result**✗ Failed****Pass with rectification**

Nearside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12

2022-01-27 16:49

MOT test number

578114457772

Result**✓ Passed**

**MOT #11** 2021-02-01 10:09**MOT test number** 467476425328**Result** ✓ Passed**MOT #10** 2020-09-03 10:59**MOT test number** 261651896509**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Coolant leak of engine near to metal housing**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Nail in the tyre tread**MOT #9** 2019-08-30 14:50**MOT test number** 969661724758**Result** ✓ Passed**MOT #8** 2018-09-15 07:55**MOT test number** 914086489814**Result** ✓ Passed**MOT #7** 2018-09-15 07:55**MOT test number** 205099411577**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #6** 2017-09-16 08:49**MOT test number** 252161587230**Result** ✓ Passed

**MOT #5** 2016-09-19 09:27**MOT test number** 158381671431**Result** ✓ Passed**MOT #4** 2015-09-02 10:38**MOT test number** 721886683678**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear tyre innear sidewall perished/cracking**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-08-29 09:35**MOT test number** 486041044214**Result** ✓ Passed**MOT #2** 2013-09-19 13:39**MOT test number** 937022363229**Result** ✓ Passed**MOT #1** 2013-06-11 13:50**MOT test number** 487802563142**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-07-30
Last registration	2024-02-08
Complete history	See info



Registration #1	2010-07-30	26 mi
Registration #2	2013-06-11	4.730 mi
Registration #3	2013-09-19	5.160 mi
Registration #4	2014-08-29	9.198 mi
Registration #5	2015-09-02	12.290 mi
Registration #6	2016-09-19	15.124 mi
Registration #7	2017-09-16	18.568 mi
Registration #8	2018-09-15	21.964 mi
Registration #9	2018-09-15	21.964 mi
Registration #10	2019-09-15	25.377 mi
Registration #11	2019-09-15	25.377 mi
Registration #12	2019-09-15	25.377 mi
Registration #13	2019-09-15	25.377 mi
Registration #14	2019-09-15	25.377 mi
Registration #15	2019-09-15	25.377 mi
Registration #16	2019-09-15	25.377 mi
Registration #17	2019-09-15	25.377 mi
Registration #18	2019-09-15	25.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203