




General information

Make	BMW
Model	X3 XDRIVE18D SE
Colour	Black
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.000 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-04
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	21
Total items failed	23

MOT #18	2023-10-24 15:53
MOT test number	600859175481
Result	✓ Passed
Next expiry date	2024-10-27
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17	2023-10-23 11:54
MOT test number	156344216769
Result	✗ Failed
Fail	Nearside Front Service brake excessively binding (1.2.1 (f))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2022-10-28 10:44
MOT test number	934949057721
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2022-10-27 11:01

MOT test number

271469270013

Result**✗ Failed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Front Lower Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))

MOT #14

2021-10-23 10:36

MOT test number

135785477847

Result**✓ Passed****Minor**

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Offside Rear Suspension arm damaged but not seriously weakened (5.3.3 (b) (i))

Advice

Nearside Rear backing plate corroded

Advice

Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #13** 2021-10-21 11:49**MOT test number** 873789572761**Result** ✗ Failed

- Fail** Nearside Rear Suspension arm damaged and seriously weakened (5.3.3 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Rear Suspension arm damaged but not seriously weakened (5.3.3 (b) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear backing plate corroded
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #12 2020-10-22 16:06**MOT test number** 497281423691**Result** ✓ Passed**MOT #11** 2019-10-16 08:19**MOT test number** 660221751602**Result** ✓ Passed

**MOT #10** 2019-10-10 10:59**MOT test number** 220211110510**Result** ✗ Failed**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Front exhaust clamp cracked**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Rear Inner Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Suspension arm damaged and seriously weakened rear most (5.3.3 (b) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))**MOT #9** 2018-10-13 12:46**MOT test number** 577120559339**Result** ✓ Passed**Advice** Offside Rear drive shaft gaiter slightly deteriorated**Advice** Wheel bearing slightly noisy rear (5.1.3 (b) (i))**MOT #8** 2017-12-08 10:08**MOT test number** 463932566802**Result** ✓ Passed**Advice** Wiper linkage worn however clearing screen**MOT #7** 2016-11-17 17:35**MOT test number** 593055666597**Result** ✓ Passed

**MOT #6** 2015-12-03 14:42**MOT test number** 868889205046**Result** ✓ Passed**MOT #5** 2014-12-09 11:10**MOT test number** 805483544324**Result** ✓ Passed**MOT #4** 2014-12-08 09:56**MOT test number** 369452744312**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #3** 2013-11-01 14:27**MOT test number** 117075103362**Result** ✓ Passed**MOT #2** 2012-09-25 12:35**MOT test number** 678369862254**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1	2012-09-24 09:17
MOT test number	449948362252
Result	✗ Failed
Fail	Nearside Front Wheel bolt(s) missing (4.2.A.1e)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 October 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	27 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	SL59UXE
Plate since	2019-09-29
Current registration	SL59UXE
Plate since	2019-09-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-10-09
Last registration	2023-10-24
Complete history	See info



Registration #1	2009-10-09	20 mi
Registration #2	2012-09-24	33.670 mi
Registration #3	2012-09-25	33.672 mi
Registration #4	2013-11-01	45.979 mi
Registration #5	2014-12-08	55.559 mi
Registration #6	2014-12-09	55.559 mi
Registration #7	2015-12-03	63.804 mi
Registration #8	2016-11-17	70.631 mi
Registration #9	2017-12-08	77.695 mi
Registration #10	2018-10-13	81.235 mi
Registration #11	2019-05-29	85.277 mi
Registration #12	2019-05-29	85.277 mi
Registration #13	2019-05-29	85.277 mi
Registration #14	2019-05-29	85.277 mi
Registration #15	2019-05-29	85.277 mi
Registration #16	2019-05-29	85.277 mi
Registration #17	2019-05-29	85.277 mi
Registration #18	2019-05-29	85.277 mi
Registration #19	2019-05-29	85.277 mi
Registration #20	2019-05-29	85.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1853 mm
Height	1674 mm
Length	4569 mm
Wheel base	2795 mm
Kerb weight	1740 kg
Max. allowed weight	2265 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	81597235