



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA EX
Colour	Brown
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-12-06
Pictures	58
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-14
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	19
Total items failed	12

MOT #17	2023-10-12 14:41
MOT test number	523274496545
Result	✓ Passed
Next expiry date	2024-10-14
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated SLIGHTLY LEAKING GREASE (6.1.7 (g) (ii))

**MOT #16**

2023-10-11 15:57

MOT test number

864482728287

Result**✗ Failed**

- Fail** Front Headlamp aim too low BOTH FRONT HEADLIGHTS (4.1.2 (a))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated SLIGHTLY LEAKING GREASE (6.1.7 (g) (i))
- Fail** Offside Front Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm WORN+CORDS INNER EDGE (5.2.3 (e))
- Fail** Front Windscreen wiper does not clear the windscreen effectively BOTH (3.4 (b) (ii))
- Fail** Offside Front Tyre has ply or cords exposed WORN INNER + CUT TO CORDS (5.2.3 (d) (ii))

MOT #15

2022-09-16 15:19

MOT test number

818875574595

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2021-10-12 16:20

MOT test number

160901344754

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-10-15 12:56**MOT test number** 229695016653**Result** ✓ Passed**MOT #12** 2020-10-10 11:57**MOT test number** 609225614546**Result** ✗ Failed**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**MOT #11** 2019-10-15 14:59**MOT test number** 301838931031**Result** ✓ Passed**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #10** 2019-03-11 13:31**MOT test number** 917117368975**Result** ✓ Passed**MOT #9** 2018-08-23 11:45**MOT test number** 894506615811**Result** ✓ Passed**MOT #8** 2018-02-26 14:34**MOT test number** 369397822713**Result** ✓ Passed

**MOT #7** 2017-08-31 14:58**MOT test number** 871078932898**Result** ✓ Passed**Advice** Nearside Rear Tyre wearing on inner edge**Advice** Offside Front tyre wearing on edges**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front tyre wearing on edges**MOT #6** 2017-08-31 11:37**MOT test number** 344086471849**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front tyre wearing on edges**Fail** Offside Rear Passenger's seat insecure (6.2.A.1)**Advice** Nearside Rear Tyre wearing on inner edge**Advice** Offside Front tyre wearing on edges**Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)**MOT #5** 2017-03-01 15:27**MOT test number** 813677812748**Result** ✓ Passed**MOT #4** 2016-09-07 13:34**MOT test number** 912925082785**Result** ✓ Passed



MOT #3	2016-03-17 10:58
MOT test number	191074907350
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin x2 (3.5.1g)

MOT #2	2015-09-21 10:40
MOT test number	687870079318
Result	✓ Passed

MOT #1	2015-02-17 10:23
MOT test number	249858145066
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
2 April 2024

✓

MOT

Expires:
14 October 2024

Tax status	Expired at 2 April 2024
Days left	28 days too late
MOT expiry date	14 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-30
Last registration	2023-10-12
Complete history	See info



Registration #1	2012-03-30	7 mi
Registration #2	2015-02-17	16.100 mi
Registration #3	2015-09-21	16.807 mi
Registration #4	2016-03-17	25.475 mi
Registration #5	2016-09-07	31.716 mi
Registration #6	2017-03-01	42.370 mi
Registration #7	2017-08-31	55.879 mi
Registration #8	2017-08-31	55.909 mi
Registration #9	2018-02-26	69.401 mi
Registration #10	2018-08-23	74.221 mi
Registration #11	2019-03-20	75.377 mi
Registration #12	2019-03-20	75.377 mi
Registration #13	2019-03-20	75.377 mi
Registration #14	2019-03-20	75.377 mi
Registration #15	2019-03-20	75.377 mi
Registration #16	2019-03-20	75.377 mi
Registration #17	2019-03-20	75.377 mi
Registration #18	2019-03-20	75.377 mi
Registration #19	2019-03-20	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 2023931