



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 T SE
Colour	Green
Year of manufacture	2008
Top speed	137 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.2 mpg
Consumption extra urban	38.2 mpg
Consumption combined	27.7 mpg
CO2 emission	243 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-06-30
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-03-12
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	7

MOT #16	2021-03-10 12:15
MOT test number	884170003672
Result	✓ Passed
Next expiry date	2022-03-12
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2021-03-10 11:16
MOT test number	634321555099
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #14	2020-03-13 12:26
MOT test number	340267091871
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing n/s & o/s cracked & perished around tread circumference (5.2.3 (d) (ii))
Advice	Rear Tyre worn close to legal limit/worn on edge n/s & o/s worn inner edges (5.2.3 (e))

**MOT #13** 2019-03-04 16:37**MOT test number** 842264511368**Result** ✓ Passed**Advice** N/S/F & O/S/F tyres cracking around tread circumference**Advice** N/S/R & O/S/R tyres worn inner edges**MOT #12** 2019-03-04 10:23**MOT test number** 199391170567**Result** ✗ Failed**Advice** N/S/F & O/S/F tyres cracking around tread circumference**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** N/S/R & O/S/R tyres worn inner edges**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2018-02-16 09:11**MOT test number** 125476785762**Result** ✓ Passed**Advice** Offside front inner rack joint has slight play.**Advice** Front brake discs corroded.**MOT #10** 2017-03-02 12:20**MOT test number** 510772279529**Result** ✓ Passed**MOT #9** 2016-02-29 09:55**MOT test number** 261272094270**Result** ✓ Passed

**MOT #8** 2016-02-29 09:55**MOT test number** 808916632443**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2015-03-05 11:51**MOT test number** 975934065011**Result** ✓ Passed**MOT #6** 2014-03-04 12:21**MOT test number** 368223164054**Result** ✓ Passed**Notice** Exhaust mountings heavily corroded**MOT #5** 2014-03-04 11:50**MOT test number** 985873764061**Result** ✗ Failed**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)**Notice** Exhaust mountings heavily corroded**MOT #4** 2013-03-07 13:03**MOT test number** 186626463084**Result** ✓ Passed**MOT #3** 2012-03-02 10:03**MOT test number** 337882962099**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-03-08 10:04
MOT test number	278287661025
Result	✓ Passed

MOT #1	2011-03-08 10:04
MOT test number	538417161051
Result	✗ Failed
<div>Pass with rectification</div> Registration plate lamp not working (1.1.C.1d)	



Tax & MOT check

X

Untaxed

Tax expired:  
4 November 2021

X

MOT

Expired:  
12 March 2022

Tax status	Expired at 4 November 2021
Days left	906 days too late
MOT expiry date	12 March 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-01
Last registration	2021-03-10
Complete history	<a href="#">See info</a>



Registration #1	2008-03-01	15 mi
Registration #2	2011-03-08	36.932 mi
Registration #3	2012-03-02	46.467 mi
Registration #4	2013-03-07	54.882 mi
Registration #5	2014-03-04	61.316 mi
Registration #6	2014-03-04	61.316 mi
Registration #7	2015-03-05	69.735 mi
Registration #8	2016-02-29	77.305 mi
Registration #9	2016-02-29	77.305 mi
Registration #10	2016-03-29	75.377 mi
Registration #11	2016-03-29	75.377 mi
Registration #12	2016-03-29	75.377 mi
Registration #13	2016-03-29	75.377 mi
Registration #14	2016-03-29	75.377 mi
Registration #15	2016-03-29	75.377 mi
Registration #16	2016-03-29	75.377 mi
Registration #17	2016-03-29	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1747 kg
Max. allowed weight	2280 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4233666