



General information

Make	VOLKSWAGEN
Model	BEETLE SPORT TSI 140
Colour	Beige
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	220 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	169 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-10-05
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	37
Total items failed	12

MOT #18	2023-12-09 10:41
MOT test number	851593061482
Result	✓ Passed
Next expiry date	2024-12-08
Advice	Under Tray Fitted
Advice	Under Seal Applied

**MOT #17**

2023-11-07 10:43

MOT test number

840974107622

Result**✗ Failed**

Fail Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Spring (5.3.6 (a) (i))

Advice Rear Subframe corroded, structural rigidity not significantly reduced

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Central Rear Upper Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))

Advice Both Rear Swing Arm Bushes Detiorated and worn, not resulting in excessive movement

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Exhaust Back Box Corroded

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

Advice Brake Pedal Has Travel

MOT #16

2022-11-02 17:23

MOT test number

322957752198

Result**✓ Passed**

Advice Rear exhaust box badly corroded but not blowing

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Nearside Rear handbrake low effort

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #15** 2021-09-29 07:32**MOT test number** 318309590985**Result** ✓ Passed**MOT #14** 2020-10-29 10:09**MOT test number** 184706681551**Result** ✓ Passed

- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2019-11-04 09:10**MOT test number** 227776222355**Result** ✓ Passed**MOT #12** 2018-10-08 15:28**MOT test number** 735122240202**Result** ✓ Passed**MOT #11** 2017-11-01 11:15**MOT test number** 221168489313**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Rear exhaust box outer skin corroded
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Centre exhaust clamp broken but not leaking exhaust gases

**MOT #10** 2016-10-27 08:58**MOT test number** 419921302997**Result** ✓ Passed**Advice** Rear exhaust box outer skin corroded**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**MOT #9** 2015-10-30 10:20**MOT test number** 533649424617**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust box outer skin corroded**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Coolant level low**MOT #8** 2014-09-30 10:13**MOT test number** 348963374441**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Rear exhaust box outer skin deteriorating**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Items removed from driver's view prior to test**Notice** Nearside front outer tyre sidewall deteriorating**MOT #7** 2013-10-24 13:20**MOT test number** 357767593219**Result** ✓ Passed

**MOT #6** 2013-10-24 10:56**MOT test number** 339227793487**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Rear tyres on legal limit and cracking excessively on side walls**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #5** 2012-08-24 17:05**MOT test number** 358207632435**Result** ✓ Passed**MOT #4** 2011-08-22 16:43**MOT test number** 576424431202**Result** ✓ Passed**MOT #3** 2010-08-24 16:51**MOT test number** 334176230438**Result** ✓ Passed**MOT #2** 2010-04-26 15:20**MOT test number** 150076610169**Result** ✓ Passed



MOT #1	2010-04-26 13:41
MOT test number	153696510189
Result	✗ Failed
Fail	Centre Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 December 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-04
Last registration	2023-12-09
Complete history	See info



Registration #1	2007-05-04	14 mi
Registration #2	2010-04-26	17.736 mi
Registration #3	2010-04-26	17.736 mi
Registration #4	2010-08-24	21.123 mi
Registration #5	2011-08-22	27.376 mi
Registration #6	2012-08-24	33.581 mi
Registration #7	2013-10-24	41.190 mi
Registration #8	2013-10-24	41.190 mi
Registration #9	2014-09-30	45.850 mi
Registration #10	2015-10-30	51.517 mi
Registration #11	2016-05-20	55.277 mi
Registration #12	2016-05-20	55.277 mi
Registration #13	2016-05-20	55.277 mi
Registration #14	2016-05-20	55.277 mi
Registration #15	2016-05-20	55.277 mi
Registration #16	2016-05-20	55.277 mi
Registration #17	2016-05-20	55.277 mi
Registration #18	2016-05-20	55.277 mi
Registration #19	2016-05-20	55.277 mi
Registration #20	2016-05-20	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1423 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMY 023990