



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 SPORT
Colour	Blue
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





MOT history

MOT expiry date	2024-10-08
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	45
Total items failed	13

MOT #23	2023-10-09 11:04
MOT test number	213807335183
Result	✓ Passed
Next expiry date	2024-10-08
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Tyre worn close to legal limit/worn on edge ns/os (5.2.3 (e))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output ns/os (4.1.4 (b))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside outer body damage front/rear
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened ns/os (1.1.14 (a) (ii))

**MOT #22**

2023-10-06 15:21

**MOT test number**

557819876277

**Result****✗ Failed**

- Advice** Nearside outer body damage front/rear
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Tyre worn close to legal limit/worn on edge ns/os (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output ns/os (4.1.4 (b))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot missing (6.1.7 (g) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened ns/os (1.1.14 (a) (ii))
- MAJOR** Nearside Front Direction indicator not working (4.4.1 (a) (ii))

**MOT #21**

2022-10-01 10:58

**MOT test number**

613159010501

**Result****✓ Passed**

- Minor** Suspension component ball joint dust cover severely deteriorated both (5.3.4 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20**

2022-10-01 10:31

**MOT test number**

101756821416

**Result****✗ Failed**

- MAJOR** Nearside Rear Position lamp missing (4.2.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Suspension component ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

**MOT #19** 2022-07-01 08:13**MOT test number** 789565005012**Result** ✗ Failed

- Minor** Front Suspension arm ball joint dust cover severely deteriorated both front (5.3.4 (b) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Front Inner Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))
- MAJOR** Horn not working (7.7 (a))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #18** 2021-09-15 10:30**MOT test number** 807568841036**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 .... (1.1.14 (a) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #17** 2021-09-15 10:30**MOT test number** 282650534070**Result** ✗ Failed

- Pass with rectification** Horn not working (7.7 (a))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 .... (1.1.14 (a) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #16** 2020-08-07 09:57**MOT test number** 112758659127**Result** ✓ Passed**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))**MOT #15** 2020-08-07 09:57**MOT test number** 189006536864**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))**MOT #14** 2020-06-10 12:00**MOT test number** 213125173100**Result** ✓ Passed**Advice** Front Wipers smearing with windscreen**Advice** Rear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear body slight damaged**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13** 2018-11-05 14:39**MOT test number** 784752298750**Result** ✓ Passed

**MOT #12** 2018-11-05 13:33**MOT test number** 959877814286**Result** ✗ Failed**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #11** 2017-10-31 17:39**MOT test number** 236213930157**Result** ✓ Passed**MOT #10** 2017-10-31 12:04**MOT test number** 657458727483**Result** ✗ Failed**Fail** Nearside Front Side repeater not working (1.4.A.2c)**MOT #9** 2016-10-13 11:22**MOT test number** 223310891733**Result** ✓ Passed**MOT #8** 2016-10-13 08:33**MOT test number** 589791158740**Result** ✗ Failed**Fail** Fuel pipe leaking (7.2.3)**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #7** 2015-09-24 07:53**MOT test number** 445994656750**Result** ✓ Passed

**MOT #6** 2015-09-24 07:53**MOT test number** 262406179177**Result** ✗ Failed**Pass with rectification** Exhaust system not adequately supported rear box clamp is broken (7.1.1)**MOT #5** 2014-06-16 17:05**MOT test number** 206617864194**Result** ✓ Passed**Notice** Front brake discs in poor condition**Notice** Front to rear brake pipe mount broken**MOT #4** 2014-06-14 14:04**MOT test number** 245895564488**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Front to rear brake pipe mount broken**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Front brake discs in poor condition**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2013-01-21 14:08**MOT test number** 497371123069**Result** ✓ Passed



MOT #2	2012-01-10 16:39
MOT test number	125870912401
Result	✓ Passed
MOT #1	2011-05-11 17:03
MOT test number	137531131144
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
8 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	8 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-06-30
Last registration	2023-10-09
Complete history	<a href="#">See info</a>



Registration #1	2008-06-30	7 mi
Registration #2	2011-05-11	2.175 mi
Registration #3	2012-01-10	2.515 mi
Registration #4	2013-01-21	10.165 mi
Registration #5	2014-06-14	21.679 mi
Registration #6	2014-06-16	21.679 mi
Registration #7	2015-09-24	29.100 mi
Registration #8	2015-09-24	29.100 mi
Registration #9	2016-10-13	33.261 mi
Registration #10	2016-10-13	33.261 mi
Registration #11	2017-10-31	36.535 mi
Registration #12	2017-10-31	36.535 mi
Registration #13	2018-10-31	39.809 mi
Registration #14	2018-10-31	39.809 mi
Registration #15	2019-10-31	43.083 mi
Registration #16	2019-10-31	43.083 mi
Registration #17	2020-10-31	46.357 mi
Registration #18	2020-10-31	46.357 mi
Registration #19	2021-10-31	49.631 mi
Registration #20	2021-10-31	49.631 mi
Registration #21	2022-10-31	52.905 mi
Registration #22	2022-10-31	52.905 mi
Registration #23	2023-10-09	56.179 mi
Registration #24	2023-10-09	56.179 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1473 mm
Length	4037 mm
Wheel base	2540 mm
Kerb weight	1288 kg
Max. allowed weight	1678 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FHBD0289660