



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 VTR
Colour	Silver
Year of manufacture	-
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-21
Pictures	13
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #13	2021-09-14 06:12
MOT test number	407707161687
Result	✓ Passed
Next expiry date	2022-09-13

MOT #12	2020-12-08 16:30
MOT test number	733750245563
Result	✓ Passed

Advice Corrosion to rear chassis and inner sills

MOT #11	2019-11-20 09:28
MOT test number	688977079368
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2018-09-14 15:35
MOT test number	586261947321
Result	✓ Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #9	2017-09-04 15:48
MOT test number	792898568509
Result	✓ Passed

MOT #8	2017-08-31 15:33
MOT test number	646512754992
Result	✗ Failed

Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #7** 2016-09-13 16:18**MOT test number** 432561477553**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-08-24 09:59**MOT test number** 568376835287**Result** ✓ Passed**MOT #5** 2014-09-05 16:44**MOT test number** 738668844226**Result** ✓ Passed**MOT #4** 2014-09-04 11:43**MOT test number** 446087444292**Result** ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #3 2013-09-13 13:52**MOT test number** 397936053454**Result** ✓ Passed

- Notice** Nearside front constant velocity joint gaiter insecure
- Notice** All 4 tyres badly perished and cracked.



MOT #2	2013-09-13 09:06
MOT test number	286256153237
Result	✗ Failed
<div><div>Notice</div>Nearside front constant velocity joint gaiter insecure</div> <div><div>Fail</div>Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)</div> <div><div>Notice</div>All 4 tyres badly perished and cracked.</div>	

MOT #1	2012-08-29 09:12
MOT test number	218842042229
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-16
Last registration	2021-09-14
Complete history	See info



Registration #1	2009-09-16	25 mi
Registration #2	2012-08-29	15.705 mi
Registration #3	2013-09-13	24.284 mi
Registration #4	2013-09-13	24.284 mi
Registration #5	2014-09-04	18.250 mi
Registration #6	2014-09-05	31.706 mi
Registration #7	2015-08-24	39.859 mi
Registration #8	2016-09-13	57.420 mi
Registration #9	2016-09-13	57.420 mi
Registration #10	2016-09-13	57.420 mi
Registration #11	2016-09-13	57.420 mi
Registration #12	2016-09-13	57.420 mi
Registration #13	2016-09-13	57.420 mi
Registration #14	2016-09-13	57.420 mi
Registration #15	2016-09-13	57.420 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	990 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST36122073