



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Brown
Year of manufacture	2014
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





MOT history

MOT expiry date	2025-02-21
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #10 2024-01-23 10:36

MOT test number 835176279413

Result ✓ Passed

Next expiry date 2025-02-21

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened and offside rear (1.1.14 (a) (ii))

Advice Power steering component has slight seepage from a component steering rack (2.1.5 (a))

MOT #9 2023-02-16 11:41

MOT test number 509639664439

Result ✓ Passed

Advice Power steering component has slight seepage from a component Steering rack (2.1.5 (a))

MOT #8 2023-02-16 11:12

MOT test number 987433729154

Result ✗ Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Power steering component has slight seepage from a component Steering rack (2.1.5 (a))

**MOT #7**

2022-02-07 16:33

MOT test number

197193519986

Result

✓ Passed

- Advice** Nearside Front Nail in tyre leaking
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust front flexi pipe slight gas blow.

MOT #6

2022-02-07 16:15

MOT test number

493566068735

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust front flexi pipe slight gas blow.
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Nail in tyre leaking
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #5

2021-02-15 11:30

MOT test number

219232788954

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2020-02-07 08:51**MOT test number** 612113706096**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2019-02-15 13:58**MOT test number** 858404073122**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2018-02-20 14:31**MOT test number** 168686692149**Result** ✓ Passed**Advice** Offside Rear tyre starting to crack**MOT #1** 2017-02-22 09:45**MOT test number** 693552580489**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 February 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-06-11
Last registration	2024-01-23
Complete history	See info



Registration #1	2014-06-11	15 mi
Registration #2	2017-02-22	8.784 mi
Registration #3	2018-02-20	23.044 mi
Registration #4	2019-02-15	37.301 mi
Registration #5	2020-02-07	53.746 mi
Registration #6	2021-02-15	62.909 mi
Registration #7	2022-02-22	75.277 mi
Registration #8	2023-02-20	85.277 mi
Registration #9	2024-02-20	95.277 mi
Registration #10	2025-02-20	105.277 mi
Registration #11	2026-02-20	115.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19EF8057LDD