



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	A 200 A200 CDI BLUEEFFICIENCY AMG SP
Colour	White
Year of manufacture	2013
Top speed	130 mph
0 - 100 km/h	9.3 seconds
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 kW / 136 HP / 136 BHP
Max. torque	300 Nm at 1.600 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	121 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-11-13
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-13
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #11	2024-01-10 16:52
MOT test number	934984467978
Result	✓ Passed
Next expiry date	2025-01-13
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10	2024-01-10 14:56
MOT test number	160800423316
Result	✗ Failed
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9	2023-01-14 09:59
MOT test number	908472708579
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8** 2022-01-10 16:38**MOT test number** 112390461425**Result** ✓ Passed**MOT #7** 2022-01-10 13:42**MOT test number** 498111379300**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed split sidewall (5.2.3 (d) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords cuts to wall (5.2.3 (d) (i))**MOT #6** 2021-06-19 13:57**MOT test number** 843937770897**Result** ✓ Passed**Advice** Nearside Front possible crack on inner side wall wheel**Advice** Both rear tyres have deep cuts on centre of tread, no cords exposed**Advice** Offside Front Tyre slightly damaged Deep cuts on inner and outer side wall (5.2.3 (d) (ii))**MOT #5** 2021-06-19 10:55**MOT test number** 479335927061**Result** ✗ Failed**Advice** Nearside Front possible crack on inner side wall wheel**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Both rear tyres have deep cuts on centre of tread, no cords exposed**Advice** Offside Front Tyre slightly damaged Deep cuts on inner and outer side wall (5.2.3 (d) (ii))



MOT #4	2020-03-07 12:31
---------------	------------------

MOT test number	430482373385
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to legal limit/worn on edge 225/40r18 (5.2.3 (e))
---------------	--

Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
---------------	---

MOT #3	2019-01-16 12:47
---------------	------------------

MOT test number	276069097860
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2018-02-03 10:19
---------------	------------------

MOT test number	443843399416
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2016-11-16 05:39
---------------	------------------

MOT test number	906601180913
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
13 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-28
Last registration	2024-01-10
Complete history	See info



Registration #1	2013-09-28	21 mi
Registration #2	2016-11-16	31.746 mi
Registration #3	2018-02-03	38.981 mi
Registration #4	2019-01-16	44.150 mi
Registration #5	2020-03-07	49.062 mi
Registration #6	2021-06-19	53.987 mi
Registration #7	2021-06-19	53.987 mi
Registration #8	2022-06-20	55.277 mi
Registration #9	2022-06-20	55.277 mi
Registration #10	2022-06-20	55.277 mi
Registration #11	2022-06-20	55.277 mi
Registration #12	2022-06-20	55.277 mi
Registration #13	2022-06-20	55.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1433 mm
Length	4292 mm
Wheel base	2699 mm
Kerb weight	1345 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	65190131985150