



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Silver
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-02-28
Pictures	25
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-16
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	36
Total items failed	7

MOT #19	2024-01-17 11:19
MOT test number	349990077923
Result	✓ Passed
Next expiry date	2025-01-16
Advice	Exhaust has a minor leak of exhaust gases exhaust slightly blowing at the center joint (6.1.2 (a))

MOT #18	2023-01-03 15:40
MOT test number	257615414898
Result	✓ Passed

MOT #17	2022-01-04 15:01
MOT test number	941183649832
Result	✓ Passed

MOT #16	2022-01-04 15:01
MOT test number	207220766396
Result	✗ Failed
Pass with rectification	Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Both sides (6.1.7 (g) (ii))

**MOT #15** 2021-01-11 10:51**MOT test number** 879196735058**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2019-07-12 12:05**MOT test number** 104248703713**Result** ✓ Passed**MOT #13** 2019-07-12 12:05**MOT test number** 672974223314**Result** ✗ Failed**Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))**MOT #12** 2018-06-28 15:50**MOT test number** 316047249244**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged**Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #11**

2018-06-26 15:37

MOT test number

598883542899

Result**✗ Failed****DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Non obligatory mirror damaged**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MOT #10**

2017-07-03 11:20

MOT test number

517088160019

Result**✓ Passed****Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front wheel tight to turn by hand**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Nail in tyre**Advice** Offside Rear Outer Tyre sidewall perished

**MOT #9** 2016-06-30 09:26**MOT test number** 164586182221**Result** ✓ Passed**Advice** Offside rear tyre outer sidewall perished**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Non obligatory mirror damaged**MOT #8** 2015-07-08 13:19**MOT test number** 908299185146**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #7** 2015-07-08 13:19**MOT test number** 386739885171**Result** ✓ Passed**MOT #6** 2014-07-11 15:06**MOT test number** 665202694198**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Both rear tyres outer sidewalls perished**Notice** Items removed from driver's view prior to test

**MOT #5** 2014-07-10 16:54**MOT test number** 257081494411**Result** ✗ Failed**Notice** Items removed from driver's view prior to test**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Both rear tyres outer sidewalls perished**MOT #4** 2013-07-08 15:35**MOT test number** 977159183161**Result** ✓ Passed**MOT #3** 2013-07-08 13:47**MOT test number** 175879883109**Result** ✗ Failed**Notice** Engine warning light on**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2012-06-22 14:23**MOT test number** 818914672138**Result** ✓ Passed**MOT #1** 2011-07-01 12:23**MOT test number** 339842581122**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-11
Last registration	2024-01-17
Complete history	See info



Registration #1	2008-07-11	9 mi
Registration #2	2011-07-01	14.183 mi
Registration #3	2012-06-22	16.007 mi
Registration #4	2013-07-08	20.534 mi
Registration #5	2013-07-08	20.534 mi
Registration #6	2014-07-10	27.087 mi
Registration #7	2014-07-11	27.090 mi
Registration #8	2015-07-08	19.792 mi
Registration #9	2015-07-08	29.416 mi
Registration #10	2016-06-30	32.189 mi
Registration #11	2017-07-03	34.719 mi
Registration #12	2018-06-30	35.277 mi
Registration #13	2019-06-30	35.277 mi
Registration #14	2020-06-30	35.277 mi
Registration #15	2021-06-30	35.277 mi
Registration #16	2022-06-30	35.277 mi
Registration #17	2023-06-30	35.277 mi
Registration #18	2024-01-17	35.277 mi
Registration #19	2024-01-17	35.277 mi
Registration #20	2024-01-17	35.277 mi
Registration #21	2024-01-17	35.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141