



 **SN09FNY**

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-18
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	35
Total items failed	17

MOT #18	2023-06-14 10:03
MOT test number	558264274489
Result	✓ Passed
Next expiry date	2024-06-18
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2023-06-09 10:34
MOT test number	617057896214
Result	✗ Failed
Fail	Nearside Rear Leaf spring fractured (5.3.1 (b) (i))
Fail	Offside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt O/S/F lower ball joint (5.3.4 (b) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Windscreen washer not working (3.5 (a))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Rear Leaf spring fractured (5.3.1 (b) (i))
Advice	Nearside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Nearside Front Outline marker lamp not working (4.2.1 (a) (ii))

**MOT #16**

2022-06-10 09:40

MOT test number

764970866698

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened N/S&O/S (1.1.14 (a) (ii))**Minor** Front Suspension arm ball joint dust cover severely deteriorated N/S&O/S (5.3.4 (b) (i))**Advice** Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #15**

2022-06-10 09:40

MOT test number

320106650629

Result

✗ Failed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Front Suspension arm ball joint dust cover severely deteriorated N/S&O/S (5.3.4 (b) (i))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened N/S&O/S (1.1.14 (a) (ii))**MOT #14**

2021-06-10 08:52

MOT test number

365855982171

Result

✓ Passed

MOT #13

2020-06-19 09:47

MOT test number

673964189128

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2020-06-19 08:22

MOT test number

279901261403

Result**✗ Failed****Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Headlamp aim too low (4.1.2 (a))**MOT #11**

2019-01-17 13:23

MOT test number

591973995229

Result**✓ Passed****Advice** Offside Front Corrosion in engine bay.**Advice** Offside Front Coil spring worn (5.3.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Corrosion in engine bay.**Advice** Rear Corrosion on bumper plate.**Advice** Oil leak, but not excessive (8.4.1 (a) (i))



MOT #10	2019-01-17 09:28
MOT test number	642028867241
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Coil spring worn (5.3.1 (b) (i))
Advice	Offside Front Corrosion in engine bay.
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Front Corrosion in engine bay.
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Corrosion on bumper plate.

MOT #9	2018-01-12 14:58
MOT test number	892269950260
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2018-01-12 10:23**MOT test number** 161003236167**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2017-01-18 11:20**MOT test number** 513160155586**Result** ✓ Passed**Advice** Nearside Rear has a deep chip out of the side wall but no cord is showing**MOT #6** 2016-01-27 10:45**MOT test number** 684543313205**Result** ✓ Passed**MOT #5** 2015-01-14 10:34**MOT test number** 535654215073**Result** ✓ Passed



MOT #4	2015-01-13 11:51
MOT test number	738653515012
Result	✗ Failed
Fail	Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
Fail	Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #3	2014-04-22 14:14
MOT test number	136612114171
Result	✓ Passed

MOT #2	2013-04-20 10:26
MOT test number	865150413173
Result	✓ Passed

MOT #1	2012-04-23 09:43
MOT test number	766454812124
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
18 June 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		18 June 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SN09FNY
Plate since	2024-03-28
Current registration	SN09FNY
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-04-22
Last registration	2023-06-14
Complete history	See info



Registration #1	2009-04-22	7 mi
Registration #2	2012-04-23	50.187 mi
Registration #3	2013-04-20	70.116 mi
Registration #4	2014-04-22	86.149 mi
Registration #5	2015-01-13	90.338 mi
Registration #6	2015-01-14	90.338 mi
Registration #7	2016-01-27	97.145 mi
Registration #8	2017-01-18	103.030 mi
Registration #9	2018-01-12	110.248 mi
Registration #10	2018-01-12	110.250 mi
Registration #11	2019-01-22	110.250 mi
Registration #12	2019-01-22	110.250 mi
Registration #13	2019-01-22	110.250 mi
Registration #14	2019-01-22	110.250 mi
Registration #15	2019-01-22	110.250 mi
Registration #16	2019-01-22	110.250 mi
Registration #17	2019-01-22	110.250 mi
Registration #18	2019-01-22	110.250 mi
Registration #19	2019-01-22	110.250 mi
Registration #20	2019-01-22	110.250 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	9R16420