



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D4 SE
Colour	Red
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	175 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-12
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-16
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	18
Total items failed	5

MOT #16	2023-11-17 12:33
MOT test number	490523863592
Result	✓ Passed
Next expiry date	2024-11-16
Advice	UNABLE TO INSPECT REAR SEATBELTS DUE TO CONVERTIBLE WIND SHIELD

MOT #15	2022-11-12 11:40
MOT test number	286755513367
Result	✓ Passed

MOT #14	2021-11-09 12:28
MOT test number	924104496902
Result	✓ Passed

MOT #13	2020-10-30 13:38
MOT test number	800748787423
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2020-10-30 12:56

MOT test number

634053055816

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11**

2019-10-16 14:59

MOT test number

230505925001

Result**✓ Passed****Advice** Nearside Front Tyre worn on inner edge**MOT #10**

2019-10-16 12:49

MOT test number

512596458139

Result**✗ Failed****Advice** Nearside Front Tyre worn on inner edge**MAJOR** Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #9**

2018-10-16 13:17

MOT test number

570365182133

Result**✓ Passed**

**MOT #8** 2018-10-15 09:20**MOT test number** 150270626102**Result** ✗ Failed**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MOT #7** 2017-10-20 15:08**MOT test number** 450722722849**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2016-11-07 10:13**MOT test number** 877011951124**Result** ✓ Passed**MOT #5** 2015-10-27 18:25**MOT test number** 253630193046**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-10-27 11:14**MOT test number** 972459370237**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #3** 2014-10-30 13:15**MOT test number** 165543304364**Result** ✓ Passed**MOT #2** 2013-11-14 09:59**MOT test number** 358118713366**Result** ✓ Passed**MOT #1** 2013-11-14 09:59**MOT test number** 299208713324**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
16 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-13
Last registration	2023-11-17
Complete history	See info



Registration #1	2010-11-13	16 mi
Registration #2	2013-11-14	17.872 mi
Registration #3	2014-10-30	29.306 mi
Registration #4	2015-10-27	39.238 mi
Registration #5	2015-10-27	39.239 mi
Registration #6	2016-11-07	45.602 mi
Registration #7	2017-10-20	51.654 mi
Registration #8	2018-10-15	59.809 mi
Registration #9	2018-10-16	59.810 mi
Registration #10	2019-10-16	59.811 mi
Registration #11	2019-10-16	59.812 mi
Registration #12	2019-10-16	59.813 mi
Registration #13	2019-10-16	59.814 mi
Registration #14	2019-10-16	59.815 mi
Registration #15	2019-10-16	59.816 mi
Registration #16	2019-10-16	59.817 mi
Registration #17	2019-10-16	59.818 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1785 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	825923