





report date: 2024-03-29

General information

Make	LAND ROVER
Model	RANGE ROVER SPORT SDV6 HSE
Colour	Black
Year of manufacture	2018
Top speed	140 mph
0 - 100 km/h	7.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	225 kW / 306 HP / 306 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/11



VO18ZXB report date: 2024-03-29

Internet history

Entry 3

Date 2021-07-18

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2021-06-29
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

, -		
Date	2021-06-29	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2025-03-21
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #5	2024-03-14 10:44
MOT test number	853580303768
Result	✓ Passed
Next expiry date	2025-03-21

MOT #4		2023-03-21 11:29
MOT test	number	904929433546
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn outer edg	e (5.2.3 (e))
Advice	Front number plate cracked	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing slightly damaged	ged (5.2.3 (d) (ii))
Advice	Offside Rear Nail in tyre	


MOT #3	2022-03-22 16:12
MOT test number	122708236584
Result	✓ Passed
Advice Nearside Rear Nail in tyre	

CarCheck.co.uk page 3/11



report date: 2024-03-29

2022-03-21 09:48 **MOT** #2 319733591001 **MOT** test number Result × Failed Fail Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Rear Nail in tyre Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this LAND ROVER had different number plates. deer of plates furthe scinors

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-25
Last registration	2024-03-14
Complete history	See info



Registration #1	2018-04-25	9 mi
Registration #2	2021-04-23	23.470 mi
Registration #3		11.777 es
Registration #4		0.00 44
Registration #5		11.777 mi
Registration #6		11.777 ea
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



VO18ZXB
report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	2073 mm
Height	1803 mm
Length	4879 mm
Wheel base	2923 mm
Kerb weight	2178 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	86 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1221844306DT

CarCheck.co.uk page 11/11