





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Grey
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/14



# Internet history

## Entry 1

Date 2022-01-09

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



# MOT history

MOT expiry date	2024-09-04
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	25
Total items failed	11

MOT #18		2023-08-30 15:18
MOT test	number	369696704314
Result		✓ Passed
Next expi	y date	2024-09-04
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perished and cr	racking (5.2.3 (d) (ii))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Exhaust corroded	
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both	n front (1.1.14 (a) (ii))
Advice (ii))	Front Tyre slightly damaged/cracking or perishing both front tyres perish	ned and cracking (5.2.3 (d)
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/14



KY06GLV

report date: 2024-03-28

**MOT #17** 2023-08-21 15:24

**MOT test number** 621561580718

Result X Failed

**Fail** Offside Rear Torsion bar end fixing loose to the extent that relative movement is visible Rear bush bearing excessive movement (5.3.1 (a) (ii))

Fail
Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Exhaust System corroded

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16 2022-09-05 14:34

MOT test number 950547459833

Result \( \sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/14



MOT #15 2021-08-23 09:01

**MOT test number** 286358998071

Minor

Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14** 2020-05-19 13:58

MOT test number 835538269890

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13 2019-04-29 17:37

**MOT test number** 598066514990

**Result** ✓ Passed

MOT #12 2018-05-25 11:05

**MOT test number** 973633513200

**Result** 
✓ Passed

**MOT #11** 2017-06-23 14:39

**MOT test number** 576513215957

**Result** ✓ Passed

**MOT #10** 2016-03-18 15:56

**MOT test number** 825836285212

MOT #9 2015-03-17 13:15

**MOT test number** 768746675071

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

CarCheck.co.uk page 5/14



KY06GLV

report date: 2024-03-28

MOT #8	2014-02-28 16:38
MOT test number	688139454093
Result	✓ Passed
MOT #7	2013-03-20 11:25
MOT test number	906189473072
Result	✓ Passed
MOT #6	2012-03-07 11:38
MOT test number	568167862070
Result	✓ Passed
Notice Front disks worn	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #5	2012-03-07 11:38
MOT test number	898237962088
Result	<b>★</b> Failed
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Front Brake pad	(s) wearing thin (3.5.1g)
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
<b>Notice</b> Front disks worn	
Pass with rectification another lamp (1.1.A.3f)	Offside Rear Rear position lamp(s) adversely affected by the operation of

MOT #4	2011-03-04 09:40
MOT test number	827193561039
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/14



MOT #3

MOT test number

649253161098

Result

Pass with rectification

Nearside Front Headlamp not working on dipped beam (1.7.5a)

MOT #2	2010-03-18 09:29
MOT test number	363197370050
Result	<b>✓</b> Passed
MOT #1	2009-02-28 11:50
MOT test number	432569059021
Result	✓ Passed

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	4 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
**************************************	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes  See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	200-0-0
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-08
Last registration	2023-08-30
Complete history	See info



Registration #1	2006-03-08	16 mi
Registration #2	2009-02-28	18.811 mi
Registration #3	2010-03-18	23.466 mi
Registration #4	2011-03-04	28.257 mi
Registration #5	2012-03-07	32.079 mi
Registration #6	2013-03-20	34.882 mi
Registration #7	2014-02-28	37.343 mi
Registration #8	2015-03-17	40.953 mi
Registration #9	2016-03-18	44.541 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

# Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

**Engine number** FST65298536