



report date: 2022-08-09

General information

Make	ABARTH
Model	GRAND PUNTO ABARTH
Colour	White
Year of manufacture	2009
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	201 Nm at 5.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	162 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-19
Pictures	14
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-08-24
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	40
Total items failed	18

MOT #19 2023-08-19 10:49**MOT test number** 719679136766**Result** ✓ Passed**Next expiry date** 2024-08-24

- Advice** Front Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing outer edge (5.2.3 (e))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive top spring seats/chassis legs corroded (5.3.6 (a) (i))

MOT #18 2023-08-17 12:53**MOT test number** 162578687383**Result** ✗ Failed

- Advice** Front Coil spring corroded both sides (5.3.1 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases centre of exhaust (6.1.2 (a))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive top spring seats/chassis legs corroded (5.3.6 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing outer edge (5.2.3 (e))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits due to exhaust leak (8.2.1.2 (c))

**MOT #17**

2022-08-25 16:04

MOT test number

347594183033

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))**Advice** ABS pump mounting bracket slight corrosion**MOT #16**

2022-08-25 16:04

MOT test number

920400828263

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))**Pass with rectification** Front Side repeater incorrect colour both showing slightly white (4.4.3 (a))**Advice** ABS pump mounting bracket slight corrosion**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #15**

2021-07-17 10:01

MOT test number

946091262557

Result

✓ Passed

MOT #14

2020-07-09 15:08

MOT test number

652212802068

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #13**

2020-07-06 11:07

MOT test number

149834756276

Result

✗ Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2019-07-11 08:01

MOT test number

193053434835

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**MOT #11**

2018-07-09 13:46

MOT test number

786871316755

Result

✓ Passed

MOT #10

2017-06-27 11:14

MOT test number

228342125157

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2017-06-26 10:23**MOT test number** 974395662023**Result** ✗ Failed**Fail** Exhaust catalytic converter missing where one was fitted as standard (7.1.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened inner face (3.5.1i)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front brake disc in such a condition that it is seriously weakened inner face (3.5.1i)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2016-06-11 08:46**MOT test number** 655238763395**Result** ✓ Passed**MOT #7** 2015-11-13 09:14**MOT test number** 313198688829**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2014-11-20 14:46

MOT test number

539124824336

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Under-trays fitted obscuring some underside components**MOT #5**

2014-11-18 16:47

MOT test number

615562224368

Result

✗ Failed

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Rear brake caliper has restricted free movement (3.5.1k)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Under-trays fitted obscuring some underside components**MOT #4**

2014-06-02 09:47

MOT test number

297833954464

Result

✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

**MOT #3** 2013-06-06 13:01**MOT test number** 657347053109**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2013-06-05 12:15**MOT test number** 585836353156**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2012-05-31 11:14**MOT test number** 247612952408**Result** ✓ Passed**Notice** Front brake discs corroded inner faces.



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
24 August 2024

Tax status

Valid until 1 May

Days left

4

MOT expiry date

24 August 2024

Full MOT history[See MOT history](#)

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this ABARTH? How many owners did this ABARTH have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this ABARTH had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled. If not, and you buy this ABARTH then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this ABARTH is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-06-05
Last registration	2023-08-19
Complete history	See info



Registration #1	2009-06-05	15 mi
Registration #2	2012-05-31	33.874 mi
Registration #3	2013-06-05	44.174 mi
Registration #4	2013-06-06	44.174 mi
Registration #5	2014-06-02	51.119 mi
Registration #6	2014-11-18	56.369 mi
Registration #7	2014-11-20	56.370 mi
Registration #8	2015-11-13	67.969 mi
Registration #9	2016-06-11	74.610 mi
Registration #10	2017-06-26	78.774 mi
Registration #11	2017-06-27	78.775 mi
Registration #12	2018-06-26	85.377 mi
Registration #13	2018-06-27	85.377 mi
Registration #14	2019-06-26	91.979 mi
Registration #15	2019-06-27	91.979 mi
Registration #16	2020-06-26	98.581 mi
Registration #17	2020-06-27	98.581 mi
Registration #18	2021-06-26	105.183 mi
Registration #19	2021-06-27	105.183 mi
Registration #20	2022-06-26	111.785 mi
Registration #21	2022-06-27	111.785 mi

More info >

**Dimensions & weight**

Width	1726 mm
Height	1490 mm
Length	4041 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1338774