



LRIKKKB

report date: 2024-03-28

General information

Make	FIAT
Model	500 C C LOUNGE DUALOGIC
Colour	Black
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	61.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	92 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-03
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-12
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	32
Total items failed	20

MOT #182023-12-05 11:15

MOT test number562027225450

Result✓ Passed

Next expiry date2024-12-12

- Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing Dot 34/14 (5.2.3 (d) (ii))
- Minor

Offside Front Windscreen wiper blade defective Aero blade (3.4 (b) (i))
- Advice

Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17**

2023-12-04 13:54

MOT test number

273507716471

Result**✗ Failed**

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed On inner edge (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Minor** Offside Front Windscreen wiper blade defective Aero blade (3.4 (b) (i))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords On side walls (5.2.3 (d) (i))
- Fail** Nearside Front Tyre has ply or cords exposed On inner edge 195/45r16 (5.2.3 (d) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Dot 34/14 (5.2.3 (d) (ii))
- Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16** 2022-12-12 13:51**MOT test number** 599769434727**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15** 2022-12-12 12:58**MOT test number** 780216388443**Result** ✗ Failed**Fail** Front Headlamp aim projected beam image is obviously incorrect Both (4.1.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2021-12-13 14:14**MOT test number** 184780698999**Result** ✓ Passed**Advice** Nearside Front Shock absorbers have a slightly worn bush**MOT #13** 2021-05-14 13:10**MOT test number** 410362076508**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** O/S/F TYRE ON THE LIMIT

**MOT #12** 2021-05-14 10:02**MOT test number** 164985415289**Result** ✗ Failed**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** O/S/F TYRE ON THE LIMIT**MOT #11** 2020-05-18 11:16**MOT test number** 960469429058**Result** ✓ Passed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10** 2020-05-18 11:16**MOT test number** 811435373836**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect bulb in wrong (4.1.2 (c))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2019-03-20 11:57**MOT test number** 732050683671**Result** ✓ Passed**MOT #8** 2019-03-20 08:52**MOT test number** 696831405244**Result** ✗ Failed**Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #7** 2018-04-11 11:12**MOT test number** 706087722913**Result** ✓ Passed**Advice** O/s seat belt sticky**MOT #6** 2017-04-28 14:40**MOT test number** 528356893441**Result** ✓ Passed**MOT #5** 2017-04-26 11:44**MOT test number** 949146810772**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** N/s/f tyre worn on inside edge near the limit**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #4** 2016-04-21 08:03**MOT test number** 261746201520**Result** ✓ Passed**MOT #3** 2015-05-20 16:08**MOT test number** 256740345431**Result** ✓ Passed



MOT #2	2015-05-20 08:51
MOT test number	688310745101
Result	✗ Failed
Fail	Offside Front suspension has excessive play in an outer ball joint (2.5.B.2a)
Notice	Front brake pads approx 50% worn

MOT #1	2014-05-14 09:46
MOT test number	278194434471
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	LR11KKB
Plate since	2019-09-28
Current registration	LR11KKB
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-05-17
Last registration	2023-12-05
Complete history	See info



Registration #1	2011-05-17	11 mi
Registration #2	2014-05-14	15.130 mi
Registration #3	2015-05-20	20.343 mi
Registration #4	2015-05-20	20.343 mi
Registration #5	2016-04-21	26.305 mi
Registration #6	2017-04-26	30.146 mi
Registration #7	2017-04-28	30.187 mi
Registration #8	2018-04-11	32.026 mi
Registration #9	2019-03-20	33.801 mi
Registration #10	2019-03-20	33.801 mi
Registration #11	2019-03-20	33.801 mi
Registration #12	2019-03-20	33.801 mi
Registration #13	2019-03-20	33.801 mi
Registration #14	2019-03-20	33.801 mi
Registration #15	2019-03-20	33.801 mi
Registration #16	2019-03-20	33.801 mi
Registration #17	2019-03-20	33.801 mi
Registration #18	2019-03-20	33.801 mi
Registration #19	2019-03-20	33.801 mi
Registration #20	2019-03-20	33.801 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1395 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0030351