



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I TR
Colour	Blue
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption



Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1	
Date	2022-02-02
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-02-24
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	15
Total items failed	8

MOT #18	2023-02-05 15:19
MOT test number	34022235670
Result	✓ Passed
Next expiry date	2024-02-24

MOT #17	2023-02-05 15:19
MOT test number	966116268968
Result	✗ Failed
Pass with rectification	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #16	2022-01-29 17:47
MOT test number	261844101340
Result	✓ Passed
Advice	Front Play in steering rack inner joint(s)

MOT #15	2021-02-25 14:41
MOT test number	779043952639
Result	✓ Passed

**MOT #14** 2020-02-25 18:28**MOT test number** 919975800839**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-02-21 14:39**MOT test number** 826438952751**Result** ✓ Passed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Last row seats and seat belts not tested, items/goods loaded**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Front Tyre worn close to legal limit/worn on edge slightly damaged outer wall (5.2.3 (e))**MOT #12** 2018-02-24 11:47**MOT test number** 483105101203**Result** ✓ Passed

**MOT #11** 2018-02-23 13:20**MOT test number** 115513451538**Result** ✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10 2017-01-03 16:51**MOT test number** 953073088483**Result** ✓ Passed**MOT #9** 2015-11-09 15:11**MOT test number** 680191297760**Result** ✓ Passed**MOT #8** 2014-11-17 15:23**MOT test number** 849641124300**Result** ✓ Passed**MOT #7** 2014-09-18 09:51**MOT test number** 825121764277**Result** ✓ Passed**MOT #6** 2013-07-16 12:17**MOT test number** 208837493109**Result** ✓ Passed

**MOT #5** 2012-10-30 11:52**MOT test number** 818144702399**Result** ✓ Passed**Notice** Rear brake discs slightly worn / front brake pads low**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2012-10-30 11:52**MOT test number** 455244302409**Result** ✗ Failed**Notice** Rear brake discs slightly worn / front brake pads low**Pass with rectification** Offside Headlamp aim too high (1.8)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #3** 2012-07-19 12:40**MOT test number** 486621102271**Result** ✓ Passed**MOT #2** 2011-07-16 11:09**MOT test number** 836837091140**Result** ✓ Passed**MOT #1** 2010-07-30 12:43**MOT test number** 843981510227**Result** ✓ Passed**Notice** Nearside wiper smearing.**Notice** Front brake discs worn, inner faces rusted.



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✗
MOT

Expired:
24 February 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	24 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GV57RTO
Plate since	2019-03-29
Current registration	GV57RTO
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-01
Last registration	2023-02-05
Complete history	See info



Registration #1	2007-11-01	22 mi
Registration #2	2010-07-30	33.526 mi
Registration #3	2011-07-16	40.451 mi
Registration #4	2012-07-19	46.241 mi
Registration #5	2012-10-30	47.641 mi
Registration #6	2013-07-16	52.295 mi
Registration #7	2014-09-18	56.816 mi
Registration #8	2014-11-17	58.365 mi
Registration #9	2015-11-09	62.001 mi
Registration #10	2017-01-03	74.119 mi
Registration #11	2019-05-20	95.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number

1ZZU896971