



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Blue
Year of manufacture	2007
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-05
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-02
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	90
Total items failed	17

MOT #222023-05-09 15:41

MOT test number596049818123

Result✓ Passed

Next expiry date2024-06-02

- AdviceTow bar electrics socket hanging down
- AdviceNearside Rear Child Seat fitted not allowing full inspection of adult belt
- AdviceBoth rear tyres slightly worn on inner edges
- AdviceNearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- AdviceIntegral body structure is corroded but structural rigidity is not significantly reduced Both outer sills (6.1.1 (c) (i))
- MinorNearside Front Drive shaft joint constant velocity boot severely deteriorated Has a small hole (6.1.7 (g) (i))
- AdviceCorrosion to underside suspension components
- AdviceOffside Rear Child Seat fitted not allowing full inspection of adult belt
- AdviceOffside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #21**

2023-05-09 10:50

MOT test number

456545836750

Result**✗ Failed****MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Corrosion to underside suspension components**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated Has a small hole (6.1.7 (g) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MAJOR** Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rear slightly worn (1.1.14 (a) (ii))**Advice** Tow bar electrics socket hanging down**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Both rear tyres slightly worn on inner edges**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Integral body structure is corroded but structural rigidity is not significantly reduced Both outer sills (6.1.1 (c) (i))

**MOT #20**

2022-05-04 08:04

MOT test number

861910369896

Result

✓ Passed

- Advice** Light corrosion on front subframe
- Advice** Windscreen chipped in zone b
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt rear
- Advice** Rear subframe corroded and rear suspension components
- Advice** Slight play in steering
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #19

2021-06-03 12:00

MOT test number

968875883503

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #18

2021-06-03 10:21

MOT test number

402322699894

Result

✗ Failed

- MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #17**

2020-07-07 13:42

MOT test number

405370328253

Result

✓ Passed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #16**

2020-07-03 16:19

MOT test number

274491252398

Result

✗ Failed

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Front Exhaust has a major leak of exhaust gases front flexi / centre pipe (6.1.2 (a))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Inner tyre very worn on inner edge**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #15**

2019-05-20 11:22

MOT test number

386505265675

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14**

2019-05-18 08:57

MOT test number

624244038621

Result

✗ Failed

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- MAJOR** Nearside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- MAJOR** Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

MOT #13

2018-05-14 08:12

MOT test number

633844029610

Result

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened NS / OS (3.5.1i)
- Advice** Front TYRES WORN ON INNER EDGE
- Advice** Oil leak
- Advice** Rear TYRES WORN ON INNER EDGE
- Advice** Front Exhaust has a minor leak of exhaust gases FLEXI (7.1.2)

MOT #12

2017-05-20 10:41

MOT test number

373205485047

Result

✓ Passed

- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)
- Advice** Offside Rear spring corroded
- Advice** Trailing arm rubber bush deteriorated but not resulting in excessive movement both rear (2.4.G.2)



MOT #11	2016-05-06 14:01
MOT test number	224236094134
Result	✓ Passed
Advice	Rear seats not fitted at time of test.

MOT #10	2016-05-06 08:59
MOT test number	487663608226
Result	✗ Failed
Advice	N/s/r tyre perished. o/s/r tyre badly perished.
Advice	N/s wiper split
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Advice	Rear seats not fitted at time of test.
Fail	Offside Stop lamp not working (1.2.1b)

MOT #9	2015-04-29 16:53
MOT test number	645209815129
Result	✓ Passed
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Notice	Both rear tyres perished.

**MOT #8** 2015-04-29 10:09**MOT test number** 196979815188**Result** ✗ Failed**Fail** Front position lamp(s) not working (1.1.A.3b)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Both rear tyres perished.**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2014-04-23 17:01**MOT test number** 478173714172**Result** ✓ Passed**Notice** Front brake discs worn and lipped**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**MOT #6** 2014-04-23 11:07**MOT test number** 725713814147**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Notice** Rear brake pads low**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Notice** Front brake discs worn and lipped**Fail** Centre Stop lamp not working (1.2.1b)**Notice** Both front tyres wearing on the inner edge

**MOT #5** 2013-04-05 09:52**MOT test number** 197225593441**Result** ✓ Passed**MOT #4** 2012-04-20 12:12**MOT test number** 447941312193**Result** ✓ Passed

- Notice** Osr tyre wearing on inner edge 215/60/16
- Advice** Nearside Rear Seat belt stitching slightly frayed (5.2.2b)
- Notice** Passenger seat(s) missing at time of test
- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Both rear tyre treads lumpy

MOT #3 2011-04-28 10:14**MOT test number** 388158511125**Result** ✓ Passed



MOT #2

2011-04-27 11:39

MOT test number

957357211116

Result		✗ Failed
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Notice	Offside rear brake discs scored and damaged from lack of brake pad lining (worn metal to metal)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Outer Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Rear Brake performance not tested (3.7.A.1)	
Fail	Service brake: efficiency below requirements (3.7.B.7)	
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in nearside front tyre	
Fail	Offside Outer Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Front Brake performance not tested (3.7.A.1)	



MOT #1

2010-04-30 12:50

MOT test number

201110420478

Result

✓ Passed

- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Child seat fitted not allowing full inspection of adult belt
- Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Rear brake disc slightly scored (3.5.1h)
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Rear brake disc slightly scored (3.5.1h)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
2 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	2 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	HN07RXB
Plate since	2024-03-29
Current registration	HN07RXB
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-04-30
Last registration	2023-05-09
Complete history	See info



Registration #1	2007-04-30	9 mi
Registration #2	2010-04-30	30.881 mi
Registration #3	2011-04-27	42.260 mi
Registration #4	2011-04-28	42.260 mi
Registration #5	2012-04-20	52.740 mi
Registration #6	2013-04-05	62.743 mi
Registration #7	2014-04-23	73.471 mi
Registration #8	2014-04-23	73.471 mi
Registration #9	2015-04-29	85.247 mi
Registration #10	2015-04-29	85.247 mi
Registration #11	2016-05-06	94.860 mi
Registration #12	2016-05-06	94.860 mi
Registration #13	2016-05-06	94.860 mi
Registration #14	2016-05-06	94.860 mi
Registration #15	2016-05-06	94.860 mi
Registration #16	2016-05-06	94.860 mi
Registration #17	2016-05-06	94.860 mi
Registration #18	2016-05-06	94.860 mi
Registration #19	2016-05-06	94.860 mi
Registration #20	2016-05-06	94.860 mi
Registration #21	2016-05-06	94.860 mi
Registration #22	2016-05-06	94.860 mi
Registration #23	2016-05-06	94.860 mi
Registration #24	2016-05-06	94.860 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	6G84817
---------------	---------