





report date: 2024-03-29

General information

Make	MAZDA
Model	3 SE-L NAV
Colour	Red
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-08-10

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-09
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #8		2023-06-30 13:07
MOT test	number	209537627388
Result		✓ Passed
Next expi	ry date	2024-07-09
Advice	Nearside Front Tyre slightly damaged/cracking or perishing close to limit (5.2.3 (d) (ii))
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice	Offside Front Tyre slightly damaged/cracking or perishing close to limit (5.2.3 (d)	(ii))

MOT #7	2023-06-30 10:24
MOT test number	985562647015
Result	× Failed
Fail Offside Front Service brake excessively binding (1.2.1 (f))	
Advice Offside Front Tyre slightly damaged/cracking or perishing close to limit (5.2.3 (d) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Nearside Front Service brake excessively binding (1.2.1 (f))	
Advice Nearside Front Tyre slightly damaged/cracking or perishi	ing close to limit (5.2.3 (d) (ii))

MOT #6	2022-07-09 10:39
MOT test number	201898407924
Result	√ Passed

CarCheck.co.uk page 3/12



MOT #5 2022-07-08 10:03

MOT test number 426788955011

Result X Failed

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #4 2021-07-08 15:43

MOT test number 613192193380

MOT #3 2020-07-10 10:38

MOT test number 245002414646

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



Advice

CY17FFX report date: 2024-03-29

MOT #2 2020-07-10 10:38 724765941959 **MOT** test number Result × Failed Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i)) Pass with rectification Offside Headlamp aim too low (4.1.2 (a)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1

MOT test number

924172520545

Result

Advice COVID-19 6 MONTH EXTENSION

Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
O WILCI	,

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-07-06
Last registration	2023-06-30
Complete history	See info



Registration #1	2017-07-06	14 mi
Registration #2	2020-07-10	45.588 mi
Registration #3	2020-07-10	45.588 mi
Registration #4	2021-07-08	54.480 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1465 mm
Length	4465 mm
Wheel base	2700 mm
Kerb weight	1351 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 20877374

CarCheck.co.uk page 12/12