





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	SPRINTER 314CDI
Colour	Grey
Year of manufacture	2018
Top speed	94 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	84 kW / 114 HP / 140 BHP
Max. torque	330 Nm at 1.200 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.9 mpg
CO2 emission	218 g/km
CO2 label	K



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-06-03

Pictures 15

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	5

Total items	failed	5
MOT #5		2024-04-02 14:24
MOT test nu	ımber	983231548595
Result		✓ Passed
Next expiry	date	2025-04-01
Advice Nearside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))		
Advice (5.3.4 (a) (i))	Offside Rear Lower Anti-roll bar linkage pin or bush	worn but not resulting in excessive movement

CarCheck.co.uk page 3/11



YE18EZZ

report date: 2024-03-29

MOT #4 2024-03-28 11:24

MOT test number 776715422362

Result X Failed

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Nearside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Parking brake efficiency below requirements 76 KGF (1.4.2 (a) (i))

Fail Offside Rear Inner Tyre has a lump, caused by separation or partial failure of its structure Sidewall (5.2.3 (d) (ii))

Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Rear Parking brake efficiency below requirements 171 KGF (1.4.2 (a) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2023-03-25 09:14

MOT test number 823238525116

Result ✓ Passed

MOT #2 2022-03-24 10:21

MOT test number 341363578088

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2021-03-30 11:52

MOT test number 510469542844

Result ✓ Passed

Advice Nearside Front slight chip in screen

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	1 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date


Category

Type

Damage 2

Date
Category

Туре



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here .	

	More info >
Plate changes See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	ar uk
Plate since	
Current registration	AIN SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



YE18EZZ

report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-29
Last registration	2024-04-02
Complete history	See info



Registration #1	2018-03-29	23 mi
Registration #2	2021-03-30	115.646 mi
Registration #3	2022-03-24	149.884 mi
Registration #4		11.777 es
Registration #5		0.07 es
Registration #6		0.00 44
Registration #7		11.777 no

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
0567	
60569	
iew the complete MERCEDES-BENZ factory list for this ehicle here.	More info >

		_		
Dim	ension	<u>c </u>	MOIO	ht.
וווט	CHSIOL	אט כו	weiu	I I L

Width	1993 mm
Height	2415 mm
Length	5910 mm
Wheel base	4 mm
Kerb weight	2263 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	65195534399456

CarCheck.co.uk page 11/11