



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Black
Year of manufacture	-
Top speed	134 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 3

Date	2022-12-24
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2


Date	2022-02-19
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-12-05
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

**MOT history**

MOT #19	2023-02-03 14:03
MOT test number	539988892450
Result	✓ Passed
Next expiry date	2024-02-02

MOT #18	2021-12-21 14:09
MOT test number	663157771146
Result	✓ Passed

MOT #17	2021-03-16 12:05
MOT test number	624019230904
Result	✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened rear brake discs worn and corroded (1.1.14 (a) (ii))

MOT #16	2021-03-05 16:09
MOT test number	663148656298
Result	✗ Failed

- Fail** Power steering malfunctioning (2.1.5 (a))
- Fail** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))
- Fail** Front Tyre has ply or cords exposed inner edge on both front tyres (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened rear brake discs worn and corroded (1.1.14 (a) (ii))
- Fail** Offside Rear Tyre has ply or cords exposed perished (5.2.3 (d) (ii))

MOT #15	2019-11-26 14:35
MOT test number	465051848900
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2019-11-26 14:35**MOT test number** 360385798133**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #13** 2018-11-26 10:06**MOT test number** 173560472326**Result** ✓ Passed**MOT #12** 2017-11-28 12:58**MOT test number** 389169752516**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-11-28 14:00**MOT test number** 862895800075**Result** ✓ Passed**MOT #10** 2016-11-28 14:00**MOT test number** 978969923969**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Rear Rear position lamp(s) missing (1.1.A.3a)**MOT #9** 2015-11-30 14:08**MOT test number** 879654246919**Result** ✓ Passed

**MOT #8** 2015-11-30 14:08**MOT test number** 862804790967**Result** ✗ Failed

- Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #7 2014-12-02 09:57**MOT test number** 659006534372**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-12-02 09:57**MOT test number** 748486634387**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #5 2013-12-05 09:19**MOT test number** 168549733314**Result** ✓ Passed**MOT #4** 2013-12-05 09:19**MOT test number** 938609633319**Result** ✗ Failed

- Pass with rectification** Offside Front Headlamp aim too low and too far to the left. (1.8)

**MOT #3** 2012-12-18 09:52**MOT test number** 415213952459**Result** ✓ Passed**MOT #2** 2011-06-24 15:04**MOT test number** 265795971443**Result** ✓ Passed**Notice** Both rear wheels have been repaired (welded)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-06-21 11:26**MOT test number** 696472771104**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Suspension arm synthetic bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Both rear wheels have been repaired (welded)**Fail** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-06-30
Last registration	2023-02-03
Complete history	See info



Registration #1	2008-06-30	27 mi
Registration #2	2011-06-21	42.820 mi
Registration #3	2011-06-24	42.822 mi
Registration #4	2012-12-18	53.156 mi
Registration #5	2013-12-05	60.634 mi
Registration #6	2014-12-02	67.193 mi
Registration #7	2015-11-30	71.882 mi
Registration #8	2015-11-30	71.882 mi
Registration #9	2016-11-28	77.967 mi
Registration #10	2016-11-28	77.967 mi
Registration #11	2017-11-28	83.350 mi
Registration #12	2018-05-29	85.337 mi
Registration #13	2018-05-29	85.337 mi
Registration #14	2018-05-29	85.337 mi
Registration #15	2018-05-29	85.337 mi
Registration #16	2018-05-29	85.337 mi
Registration #17	2018-05-29	85.337 mi
Registration #18	2018-05-29	85.337 mi
Registration #19	2018-05-29	85.337 mi
Registration #20	2018-05-29	85.337 mi
Registration #21	2018-05-29	85.337 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	562489