





report date: 2024-03-28

## General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Black
Year of manufacture	2009
Top speed	144 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 сс
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-11-30

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-14
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	12
Total items failed	6

MOT #17	2024-01-15 15:56
MOT test number	134860941923
Result	<b>✓</b> Passed
Next expiry date	2025-01-14

MOT #16	2024-01-15 13:32
MOT test number	502511103819
Result	<b>X</b> Failed
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOI #15	2023-01-05 11:06
MOT test number	440135412529
Result	✓ Passed
MOT #14	2023-01-05 09:39
MOT test number	886463921119
Result	<b>X</b> Failed
Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



MOI #13	2022-01-12 11:27
MOT test number	345799959596
Result	/ Passed

MOT #12	2020-11-17 10:38
MOT test number	377524380676

Result 

Passed

**MOT #11** 2019-11-01 15:40

MOT test number 225733496784

Result Passed

**MOT #10** 2018-11-30 17:27

**MOT test number** 617184237742

**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Advice** Offside Rear Tyre cracking

MOT #9 2018-11-30 16:38

**MOT test number** 301706436787

Result × Failed

**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Rear Tyre cracking

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Front Tyre cracking

Fail

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



✓ Passed

MOT #8

MOT test number

655766605271

Result

Advice Both front tyres has cracks

MOT #7

MOT test number

Result

Advice Offside Front tyre is cracking

Advice Nearside Rear tyre has cuts on outer wall

MOT #6 2015-11-14 11:05

MOT test number 750293065636

Result ✓ Passed

MOT #5 2014-11-10 11:22

MOT test number 479474514472

Result ✓ Passed

MOT #4 2013-12-27 10:58

**MOT test number** 459101663443

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



MOT test number

Result

Pass with rectification

Offside Front Headlamp aim too low (1.8)

Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2013-01-17 14:36

MOT test number 308857913022

Result ✓ Passed

MOT #1 2012-05-30 11:04

MOT test number 165921152185

Result ✓ Passed

CarCheck.co.uk page 6/13





# Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	14 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28


## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



_	
<b></b>	history
IMMAR	

Owner matery	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NIX NIX
Plate since	
	More info >

CarCheck.co.uk page 10/13



## Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-31
Last registration	2024-01-15
Complete history	See info



Registration #1	2009-05-31	21 mi
Registration #2	2012-05-30	21.537 mi
Registration #3	2013-01-17	22.866 mi
Registration #4	2013-12-27	23.616 mi
Registration #5	2014-11-10	24.291 mi
Registration #6	2015-11-14	24.880 mi
Registration #7	2016-11-23	25.451 mi
Registration #8	2017-11-27	26.708 mi
Registration #9	2018-11-30	28.328 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg

# Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531120793

CarCheck.co.uk page 13/13