



report date: 2024-03-29

## General information

Make	NISSAN
Model	PIXO VISIA
Colour	Grey
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-05-24
Pictures	40
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2021-11-04
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	8
Total items failed	3

MOT #6	2023-05-26 10:01
MOT test number	560861190417
Result	✓ Passed
Next expiry date	2024-06-01
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #5	2023-05-26 09:59
MOT test number	510452745100
Result	✗ Failed
Fail	Offside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #4	2023-05-24 12:19
MOT test number	354391472350
Result	✗ Failed
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Offside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

**MOT #3** 2022-05-31 11:01**MOT test number** 821831117592**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2021-06-02 09:00**MOT test number** 556244326647**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #1** 2021-06-01 15:36**MOT test number** 260238798661**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✗  
**MOT**  
  
Expired:  
4 November 2021

Tax status	Valid until 1 June
Days left	33
MOT expiry date	4 November 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2011-06-30
Last registration	2023-05-26
Complete history	<a href="#">See info</a>



Registration #1	2011-06-30	24 mi
Registration #2	2011-06-30	24.277 mi
Registration #3	2021-06-01	52.730 mi
Registration #4	2021-06-02	52.730 mi
Registration #5	2023-05-26	52.777 mi
Registration #6	2023-05-26	52.777 mi
Registration #7	2023-05-26	52.777 mi
Registration #8	2023-05-26	52.777 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	133813