



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Red
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-26
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #16</b>	2020-10-15 08:50
<b>MOT test number</b>	334179440089
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-10-19
<b>Advice</b>	Offside Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #15</b>	2019-10-19 09:26
<b>MOT test number</b>	496754067189
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge inner / outer edges (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge inner / outer edges (5.2.3 (e))

<b>MOT #14</b>	2019-10-19 09:26
<b>MOT test number</b>	695639765233
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge inner / outer edges (5.2.3 (e))
<b>Pass with rectification</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge inner / outer edges (5.2.3 (e))

**MOT #13** 2018-10-16 10:53**MOT test number** 361970887869**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge very close to cords also perishing (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge very close to cords also perishing (5.2.3 (e))**Advice** Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2017-10-14 08:36**MOT test number** 388581913190**Result** ✓ Passed**MOT #11** 2017-10-14 08:36**MOT test number** 326170189364**Result** ✗ Failed**Pass with rectification** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #10** 2016-10-15 12:31**MOT test number** 871877193317**Result** ✓ Passed**MOT #9** 2015-10-20 11:41**MOT test number** 453490129418**Result** ✓ Passed

**MOT #8** 2015-10-19 14:02**MOT test number** 791628733613**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #7** 2014-10-07 17:30**MOT test number** 396450284436**Result** ✓ Passed**Notice** N/s rear tyre has cracks on inner sidewall**MOT #6** 2014-10-07 13:30**MOT test number** 975220084298**Result** ✗ Failed**Notice** N/s rear tyre has cracks on inner sidewall**Fail** Nearside Front Braking system leaking (3.6.A.1)**MOT #5** 2013-10-02 10:30**MOT test number** 769955173262**Result** ✓ Passed**MOT #4** 2013-10-02 10:30**MOT test number** 477785973234**Result** ✗ Failed**Pass with rectification** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #3	2012-10-04 13:10
MOT test number	369208072498
Result	✓ Passed
MOT #2	2011-10-07 13:13
MOT test number	486570081216
Result	✓ Passed
MOT #1	2010-10-12 09:16
MOT test number	904295580280
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	EJ57HXE
Plate since	2019-09-29
Current registration	EJ57HXE
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-11-16
Last registration	2020-10-15
Complete history	<a href="#">See info</a>



Registration #1	2007-11-16	26 mi
Registration #2	2010-10-12	18.917 mi
Registration #3	2011-10-07	23.660 mi
Registration #4	2012-10-04	28.285 mi
Registration #5	2013-10-02	32.160 mi
Registration #6	2014-10-07	36.329 mi
Registration #7	2014-10-07	36.329 mi
Registration #8	2015-10-19	38.252 mi
Registration #9	2015-10-20	38.252 mi
Registration #10	2015-10-20	38.252 mi
Registration #11	2015-10-20	38.252 mi
Registration #12	2015-10-20	38.252 mi
Registration #13	2015-10-20	38.252 mi
Registration #14	2015-10-20	38.252 mi
Registration #15	2015-10-20	38.252 mi
Registration #16	2015-10-20	38.252 mi
Registration #17	2015-10-20	38.252 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB660199901