




report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SE LUX D S40
Colour	Grey
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-07-12
Pictures	29
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-19
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	36
Total items failed	8

MOT #16 2024-03-08 15:17

MOT test number 424429898462

Result ✓ Passed

Next expiry date 2025-03-19

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Under tray loose
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Both exhaust boxes have corrosion
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #15 2023-03-20 18:32

MOT test number 394075554640

Result ✓ Passed

- Advice** Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Rear Exhaust box has some corrosion
- Advice** Rear Brake hose slightly deteriorated Both rear hoses --- outer rubber tubing cover perishing (1.1.12 (b) (ii))



MOT #14

2023-03-17 17:24

MOT test number

380449423241

Result

✗ Failed

- Advice

Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Fail

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Minor

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice

Rear Brake hose slightly deteriorated Both rear hoses --- outer rubber tubing cover perishing (1.1.12 (b) (ii))
- Advice

Rear Exhaust box has some corrosion

**MOT #13**

2023-03-03 15:33

MOT test number

404964430817

Result

✗ Failed

- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front coolant low
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Central Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Rear Unable to open boot lid
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #12

2022-03-04 09:18

MOT test number

506513030704

Result

✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2020-11-20 09:55

MOT test number

608570184128

Result

✓ Passed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #10

2019-11-12 11:31

MOT test number

334137049837

Result

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9

2019-11-12 11:31

MOT test number

328276306544

Result

✗ Failed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8

2018-11-13 12:59

MOT test number

195653172223

Result

✓ Passed

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #7	2017-11-17 10:42
---------------	------------------

MOT test number	730352653631
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2016-11-22 11:47
---------------	------------------

MOT test number	888444361190
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

MOT #5	2015-11-24 14:14
---------------	------------------

MOT test number	293378879800
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-11-13 14:50
---------------	------------------

MOT test number	577827914361
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-11-04 11:05
---------------	------------------

MOT test number	389338303365
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-11-02 15:49
---------------	------------------

MOT test number	447867002372
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2011-11-03 14:40
---------------	------------------

MOT test number	527077801317
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 March 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 AG58OZW
Plate since	2019-09-28
Current registration	 AG58OZW
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-05
Last registration	2024-03-08
Complete history	See info



Registration #1	2008-11-05	23 mi
Registration #2	2011-11-03	31.546 mi
Registration #3	2012-11-02	38.709 mi
Registration #4	2013-11-04	45.798 mi
Registration #5	2014-11-13	55.949 mi
Registration #6	2015-11-24	61.305 mi
Registration #7	2016-11-22	69.187 mi
Registration #8	2017-11-17	76.979 mi
Registration #9	2018-11-13	79.914 mi
Registration #10	2019-11-13	81.377 mi
Registration #11	2020-11-13	81.377 mi
Registration #12	2021-11-13	81.377 mi
Registration #13	2022-11-13	81.377 mi
Registration #14	2023-11-13	81.377 mi
Registration #15	2024-03-08	81.377 mi
Registration #16	2024-03-08	81.377 mi
Registration #17	2024-03-08	81.377 mi
Registration #18	2024-03-08	81.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	411629