





report date: 2024-03-28

General information

Make	ASTON MARTIN
Model	RAPIDE S V12
Colour	Silver
Year of manufacture	2015
Top speed	203 mph
0 - 100 km/h	5.3 seconds
0 - 60 mph	4.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	412 kW / 561 HP / 552 BHP
Max. torque	600 Nm at 5.000 rpm
Engine capacity	5.935 cc
Cylinders	12
Fuel type	Petrol
Consumption city	14.5 mpg
Consumption extra urban	31.0 mpg
Consumption combined	21.9 mpg
CO2 emission	300 g/km
CO2 label	М



CarCheck.co.uk page 1/12



F18J0E

report date: 2024-03-28


Internet history

Entry 1

Date 2021-08-08

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-10-05
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #9	2023-10-06 15:08
MOT test number	481306509176
Result	✓ Passed
Next expiry date	2024-10-05

MOT #8	2022-12-28 10:42
MOT test number	457809809282
Result	✓ Passed
Advice Undertrays fitted.	

MOT #7	2022-12-22 14:02
MOT test number	541153838819
Result	X Failed
Advice Undertrays fitted. Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #6	2021-11-18 14:07
MOT test number	172889087800
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

page 3/12 CarCheck.co.uk



MOT #5 2021-11-15 15:37

MOT test number 729985129028

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2020-11-18 13:11

MOT test number 891752748359

Result
✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2020-11-18 13:11

MOT test number 214378724347

Result × Failed

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



MOT #2		2019-05-09 14:39
MOT test	number	240350026189
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1		2018-05-03 13:55
MOT test	number	796155211263
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this ASTON MARTIN. See if, where and when this ASTON MARTIN had damage and the car repair costs. We also check if this ASTON MARTIN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Damage 2

Type

Date

Category
Type



Extra ASTON MARTIN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



F18J0E

report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this ASTON MARTIN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



F18J0E

More info >

report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this ASTON MARTIN? How many ASTON MARTIN have? Check it in the premium report and see all owner registrations. Do report here .	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this ASTON MARTIN had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NE NE
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this ASTON MARTIN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ASTON MARTIN has been settled.

If not, and you buy this ASTON MARTIN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ASTON MARTIN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-27
Last registration	2023-10-06
Complete history	See info



Registration #1	2015-05-27	16 mi
Registration #2	2018-05-03	17.990 mi
Registration #3	2019-05-09	22.370 mi
Registration #4	2020-11-18	30.816 mi
Registration #5	2020-11-18	30.816 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		10.777 au

More info >

CarCheck.co.uk page 11/12



Dimensions	&	weiaht

Width	2140 mm
Height	1360 mm
Length	5020 mm
Wheel base	2989 mm
Kerb weight	1990 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	AM29/40795

CarCheck.co.uk page 12/12