



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SEL TDI
Colour	White
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-03
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	28
Total items failed	6

MOT #13	2023-06-14 08:08
MOT test number	413290907371
Result	✓ Passed
Next expiry date	2024-06-22
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

MOT #12	2022-06-16 07:45
MOT test number	823756523760
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11	2021-06-23 15:27
MOT test number	720086650035
Result	✓ Passed

**MOT #10** 2020-12-01 12:59**MOT test number** 360199533184**Result** ✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9 2019-12-04 10:34**MOT test number** 572265618523**Result** ✓ Passed**MOT #8** 2018-12-13 14:55**MOT test number** 953469366940**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened all discs pitted on vehicle on inside of discs (1.1.14 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both front tyres wearing on inner edge but not close to legal limit (5.2.3 (e))

**MOT #7**

2018-12-13 11:13

MOT test number

822169352107

Result**✗ Failed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))
- Advice** Rear Rear exhaust silencer corroded & peeling
- Fail** Offside Front Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Fail** Nearside Front Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #6

2017-11-29 16:54

MOT test number

240073880321

Result**✓ Passed**

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear exhaust back box outer skin corroded
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2016-11-22 11:30**MOT test number** 711814434014**Result** ✓ Passed**Advice** Nearside Rear brake lever on caliper has slightly restricted free movement**Advice** Nearside Rear Valve stem slightly damaged (4.1.D.1e)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** No emissions detected during test**MOT #4** 2015-12-01 10:02**MOT test number** 949414690044**Result** ✓ Passed**Advice** No emissions detected on test**MOT #3** 2014-12-15 14:02**MOT test number** 467729244308**Result** ✓ Passed**MOT #2** 2014-05-23 14:04**MOT test number** 625383844171**Result** ✓ Passed**MOT #1** 2013-05-24 14:24**MOT test number** 445904243137**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
22 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-23
Last registration	2023-06-14
Complete history	See info



Registration #1	2010-06-23	20 mi
Registration #2	2013-05-24	10.729 mi
Registration #3	2014-05-23	13.138 mi
Registration #4	2014-12-15	15.212 mi
Registration #5	2015-12-01	21.206 mi
Registration #6	2016-11-22	27.997 mi
Registration #7	2017-11-29	35.543 mi
Registration #8	2018-12-13	42.912 mi
Registration #9	2019-06-20	50.377 mi
Registration #10	2020-06-20	57.842 mi
Registration #11	2021-06-20	65.307 mi
Registration #12	2022-06-20	72.772 mi
Registration #13	2023-06-20	80.237 mi
Registration #14	2024-06-20	87.702 mi
Registration #15	2025-06-20	95.167 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CAY 041769