



report date: 2024-03-29

General information

Make	DACIA
Model	LOGAN AMBIANCE SCE
Colour	White
Year of manufacture	2017
Top speed	98 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	97 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	120 g/km
CO2 label	C





MOT history

MOT expiry date	2025-02-27
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	18
Total items failed	9

MOT #19	2024-02-28 11:52
MOT test number	710665578490
Result	✓ Passed
Next expiry date	2025-02-27

MOT #18	2023-11-21 13:31
MOT test number	424037625221
Result	✓ Passed

MOT #17	2023-11-17 12:31
MOT test number	510979518470
Result	✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Emissions unable to be completed Engine idle speed not low enough , Was failing test then engine overheated (8.2.2.2 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2023-11-09 12:06**MOT test number** 160103080113**Result** ✗ Failed

Fail Emissions unable to be completed Engine idle speed not low enough , Was failing test then engine overheated (8.2.2.2 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2023-05-10 10:53**MOT test number** 749660983392**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2023-05-09 11:07**MOT test number** 344732761203**Result** ✗ Failed

Advice Wiper motor/linkage INSECURE ,Wipers/arms scratching screen

Fail Windscreen damaged and affecting the driver's view of the road Scratched screen by wipers/arms (3.2 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2022-11-09 10:44**MOT test number** 531579783372**Result** ✓ Passed

Advice Offside Front Sub-frame damaged but not seriously weakened (5.3.3 (b) (i))

**MOT #12** 2022-05-10 11:12**MOT test number** 641301007888**Result** ✓ Passed**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #11** 2022-05-09 09:46**MOT test number** 803335641799**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2021-12-06 12:02**MOT test number** 498739730031**Result** ✓ Passed**MOT #9** 2021-11-29 11:42**MOT test number** 531309895719**Result** ✗ Failed**Fail** Nearside Front Electrical wiring insecure and in contact with sharp edges (4.11 (a) (ii))**MOT #8** 2021-05-11 07:36**MOT test number** 471476278222**Result** ✓ Passed

**MOT #7** 2021-04-30 06:53**MOT test number** 649380986717**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too high and too far to the right. (4.1.2 (a))**Fail** Rear Service brake imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Front Headlamp aim too low and too far to the right. (4.1.2 (a))**Fail** Front Bumper insecure lower skirts (6.1.4 (a) (i))**MOT #6** 2020-07-23 11:10**MOT test number** 760402536878**Result** ✓ Passed**MOT #5** 2020-02-04 10:18**MOT test number** 474899377493**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #4** 2019-08-06 08:26**MOT test number** 157672604871**Result** ✓ Passed**MOT #3** 2019-02-08 09:22**MOT test number** 686257983523**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-08-09 08:50**MOT test number** 352762295094**Result** ✓ Passed



MOT #1	2018-04-24 09:55
MOT test number	210604748213
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this DACIA. See if, where and when this DACIA had damage and the car repair costs. We also check if this DACIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra DACIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this DACIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this DACIA? How many owners did this DACIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this DACIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this DACIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DACIA has been settled.

If not, and you buy this DACIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this DACIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2017-09-30
Last registration	2024-02-28
Complete history	See info



Registration #1	2017-09-30	15 mi
Registration #2	2018-04-24	11.617 mi
Registration #3	2018-08-09	17.886 mi
Registration #4	2019-02-08	27.542 mi
Registration #5	2019-08-06	36.812 mi
Registration #6	2020-02-04	46.201 mi
Registration #7	2020-07-23	49.966 mi
Registration #8	2021-04-30	56.534 mi
Registration #9	2021-05-11	56.538 mi
Registration #10	2021-11-29	56.539 mi
Registration #11	2022-05-20	56.539 mi
Registration #12	2022-05-20	56.539 mi
Registration #13	2022-05-20	56.539 mi
Registration #14	2022-05-20	56.539 mi
Registration #15	2022-05-20	56.539 mi
Registration #16	2022-05-20	56.539 mi
Registration #17	2022-05-20	56.539 mi
Registration #18	2022-05-20	56.539 mi
Registration #19	2022-05-20	56.539 mi
Registration #20	2022-05-20	56.539 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1994 mm
Height	1552 mm
Length	4501 mm
Wheel base	2635 mm
Kerb weight	1071 kg
Max. allowed weight	1555 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R044277