



**KM56VUF**

report date: 2024-03-28

General information

|                     |                   |
|---------------------|-------------------|
| Make                | AUDI              |
| Model               | A6 TDI QUATTRO SE |
| Colour              | Grey              |
| Year of manufacture | 2006              |
| Top speed           | 138 mph           |
| 0 - 60 mph          | 9.1 seconds       |
| Gearbox             | 6 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 177 BHP             |
| Max. torque             | 379 Nm at 1.400 rpm |
| Engine capacity         | 2.696 cc            |
| Cylinders               | 6                   |
| Fuel type               | Diesel              |
| Consumption city        | 25.2 mpg            |
| Consumption extra urban | 41.5 mpg            |
| Consumption combined    | 33.6 mpg            |
| CO2 emission            | 222 g/km            |
| CO2 label               | K                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-01-08 |
| MOT pass rate      | 91 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 1          |
| Total advice items | 8          |
| Total items failed | 1          |

|                  |  |
|------------------|--|
| MOT #11          | 2020-01-03 08:28   |
| MOT test number  | 319147989753   |
| Result           | ✓ Passed   |
| Next expiry date | 2021-01-08   |
| Advice           | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

|                 |  |
|-----------------|--|
| MOT #10         | 2018-12-27 12:28   |
| MOT test number | 652954377444   |
| Result          | ✓ Passed   |
| Advice          | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))      |
| Advice          | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))       |
| Advice          | Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) |

|                 |                  |
|-----------------|------------------|
| MOT #9          | 2018-01-04 14:47 |
| MOT test number | 587306204694     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #8          | 2017-01-09 14:27 |
| MOT test number | 626369173793     |
| Result          | ✓ Passed         |

**MOT #7** 2015-09-24 09:58**MOT test number** 133115281515**Result** ✓ Passed**MOT #6** 2014-10-08 12:01**MOT test number** 127811984289**Result** ✓ Passed

**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2013-10-10 10:38**MOT test number** 767473183217**Result** ✓ Passed**MOT #4** 2013-10-03 12:09**MOT test number** 315836873288**Result** ✗ Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3** 2012-09-13 14:25**MOT test number** 376277652481**Result** ✓ Passed**MOT #2** 2011-10-03 14:54**MOT test number** 605016871266**Result** ✓ Passed



|                 |  |
|-----------------|--|
| MOT #1          | 2009-10-27 09:23   |
| MOT test number | 272020209352   |
| Result          | ✓ Passed   |
| Advice          | Offside Inner Front Tyre worn close to the legal limit (4.1.E.1) |



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-09-29 |
| Current registration |            |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >





Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 12                       |
| First mileage registration | 2006-11-09               |
| Last registration          | 2020-01-03               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2006-11-09 | 26 mi      |
| Registration #2  | 2009-10-27 | 51.691 mi  |
| Registration #3  | 2011-10-03 | 85.236 mi  |
| Registration #4  | 2012-09-13 | 96.317 mi  |
| Registration #5  | 2013-10-03 | 110.701 mi |
| Registration #6  | 2013-10-10 | 110.934 mi |
| Registration #7  | 2019-05-29 | 151.277 mi |
| Registration #8  | 2019-05-29 | 151.277 mi |
| Registration #9  | 2019-05-29 | 151.277 mi |
| Registration #10 | 2019-05-29 | 151.277 mi |
| Registration #11 | 2019-05-29 | 151.277 mi |
| Registration #12 | 2019-05-29 | 151.277 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1855 mm |
| Height              | 1463 mm |
| Length              | 4933 mm |
| Wheel base          | 2759 mm |
| Kerb weight         | 1815 kg |
| Max. allowed weight | 2445 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                        |            |
|------------------------|------------|
| <b>Number of axles</b> | 2          |
| <b>Engine number</b>   | BPP 061650 |