



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Silver
Year of manufacture	-
Top speed	102 mph
0 - 60 mph	15.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	155 Nm at 1.600 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN

**MOT history**

MOT #16	2022-01-18 14:28
MOT test number	285679264445
Result	✓ Passed
Next expiry date	2023-01-17
Advice	Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Brake pad warning light on
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #15	2022-01-17 13:21
MOT test number	834610599834
Result	✗ Failed
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Brake pad warning light on
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Fail	Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14	2021-01-12 11:21
MOT test number	485635859599
Result	✓ Passed

MOT #13	2020-01-04 11:03
MOT test number	669291071447
Result	✓ Passed
Advice	Under tray covers fitted

**MOT #12** 2020-01-04 11:03**MOT test number** 581746736584**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Under tray covers fitted**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #11** 2019-01-09 17:06**MOT test number** 375597996530**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both sides (4.4.3 (a))**Advice** Front Outer cases corroded shock absorbers**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Outer exhaust box deteriorated**MOT #10** 2018-01-10 15:33**MOT test number** 284043928545**Result** ✓ Passed**MOT #9** 2017-01-07 12:29**MOT test number** 725119978393**Result** ✓ Passed**MOT #8** 2017-01-07 12:29**MOT test number** 323386663176**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #7** 2015-12-19 11:36**MOT test number** 887280594128**Result** ✓ Passed**MOT #6** 2015-12-19 11:36**MOT test number** 652932240919**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2014-12-22 11:50**MOT test number** 859016854389**Result** ✓ Passed**MOT #4** 2014-01-08 09:22**MOT test number** 906588104052**Result** ✓ Passed**Notice** O/sf and n/sf wishbone bushes slightly deteriorated**Notice** Slight bind o/sr brake**MOT #3** 2013-01-14 11:40**MOT test number** 798704813025**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #2** 2011-12-16 12:01**MOT test number** 308120251332**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-12-16 12:01**MOT test number** 945430551325**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too high (1.8)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 NV58FEX
Plate since	2019-03-29
Current registration	 NV58FEX
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-01-16
Last registration	2022-01-18
Complete history	See info



Registration #1	2009-01-16	7 mi
Registration #2	2011-12-16	41.179 mi
Registration #3	2013-01-14	53.085 mi
Registration #4	2014-01-08	64.733 mi
Registration #5	2014-12-22	71.757 mi
Registration #6	2015-12-19	75.331 mi
Registration #7	2015-12-19	75.331 mi
Registration #8	2017-01-07	76.348 mi
Registration #9	2019-01-01	76.348 mi
Registration #10	2019-01-01	76.348 mi
Registration #11	2019-01-01	76.348 mi
Registration #12	2019-01-01	76.348 mi
Registration #13	2019-01-01	76.348 mi
Registration #14	2019-01-01	76.348 mi
Registration #15	2019-01-01	76.348 mi
Registration #16	2019-01-01	76.348 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BNM309749