




report date: 2025-02-13

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Black
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-15
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2018-04-24
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	7
Total items failed	6

MOT #5 2017-04-08 10:17

MOT test number 221210077408

Result ✓ Passed

Next expiry date 2018-04-24

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2017-04-08 09:45

MOT test number 104182829591

Result ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2016-04-07 14:06

MOT test number 107431441625

Result ✓ Passed

- Advice** Nearside Front tyre on 3mm



MOT #2 2016-04-05 13:59

MOT test number 856535606558

Result ✗ Failed

- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Nearside Front tyre on 3mm
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure on tread (4.1.D.1b)

MOT #1 2015-04-09 11:44

MOT test number 205549695025

Result ✓ Passed

- Notice** N/s/r tyre on 3mm



Tax & MOT check

×
Untaxed

Tax expired:
14 April 2017

×
MOT

Expired:
24 April 2018

Tax status Expired at 14 April 2017

Days left 2894 days too late

MOT expiry date 24 April 2018

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	NU12ZDN
Plate since	2019-09-29
Current registration	NU12ZDN
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2012-04-24
Last registration	2017-04-08
Complete history	See info



Registration #1	2012-04-24	9 mi
Registration #2	2015-04-09	47.825 mi
Registration #3	2016-04-05	66.666 mi
Registration #4	2016-04-07	66.707 mi
Registration #5		
Registration #6		
Registration #7		

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2259719