





report date: 2024-03-29

## General information

| Make                | MERCEDES            |
|---------------------|---------------------|
| Model               | CLK CLK320 ELEGANCE |
| Colour              | Silver              |
| Year of manufacture | 2001                |
| Top speed           | 150 mph             |
| 0 - 60 mph          | 7.4 seconds         |
| Gearbox             | 5 speed automatic   |

## Engine & fuel consumption

| Power                   | 218 BHP             |
|-------------------------|---------------------|
| Max. torque             | 310 Nm at 3.000 rpm |
| Engine capacity         | 3.199 сс            |
| Cylinders               | 6                   |
| Fuel type               | Petrol              |
| Consumption city        | 20.3 mpg            |
| Consumption extra urban | 37.2 mpg            |
| Consumption combined    | 28.5 mpg            |
| CO2 emission            | 250 g/km            |
| CO2 label               | L                   |



CarCheck.co.uk page 1/13



MOT history

| MOT expiry date    | 2021-07-19 |
|--------------------|------------|
| MOT pass rate      | 82 %       |
| MOT passed         | 14         |
| Failed MOT tests   | 3          |
| Total advice items | 25         |
| Total items failed | 5          |

| MOT #17  | 2020-07-20 14:44 |
|--|------------------|
| MOT test number                                    | 733559445494     |
| Result   | ✓ Passed         |
| Next expiry date                                   | 2021-07-19       |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) |                  |

| MOT #16         | 2019-05-11 15:06 |
|-----------------|------------------|
| MOT test number | 941354753405     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 2/13



report date: 2024-03-29

**MOT #15** 2018-11-14 17:24 **MOT** test number 388284933664 Result **★** Failed **Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) Advice Nearside Non obligatory mirror damaged Advice Outer sill area covered Advice Some under bonnet components covered Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) **MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Advice Fuel Pipe/s corroded Advice Some under side components covered **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

| MOT #14  |   | 2017-10-02 12:10 |
|----------|---|------------------|
| MOT test | number  | 301775931279     |
| Result   |   | ✓ Passed         |
| Advice   | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |                  |
| Advice   | Fuel Pipe/s corroded  |                  |
| Advice   | Offside Front Tyre worn close to the legal limit (4.1.E.1)  |                  |

| MOT #13         | 2016-05-18 12:36 |
|-----------------|------------------|
| MOT test number | 220790122089     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/13



report date: 2024-03-29

| MOT #12  | 2015-05-28 15:52 |
|--|------------------|
| MOT test number  | 207128545185     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #11  | 2014-05-16 16:33 |
| MOT test number  | 396576434191     |
| Result   | <b>✓</b> Passed  |
|  |                  |
| MOT #10  | 2014-05-14 16:34 |
| MOT test number  | 435584034192     |
| Result   | <b>X</b> Failed  |
| Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)  |                  |
| Fail Nearside Front Brake pipe excessively corroded (3.6.B.2c) |                  |
| Fail Nearside Rear coil spring broken (2.4.C.1a)               |                  |
|  |                  |
| MOT #9   | 2013-03-04 18:30 |

| MOT #9          | 2013-03-04 18:30 |
|-----------------|------------------|
| MOT test number | 989123563040     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #8          | 2012 02 24 18:27 |

| MOT #8          | 2012-02-24 18:27 |
|-----------------|------------------|
| MOT test number | 189025352096     |
| Result          | <b>✓</b> Passed  |

| MOT #7   |   | 2011-01-19 15:26 |
|----------|---|------------------|
| MOT test | number  | 139809611080     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Front Front wheel bearing has slight play (2.5.A.3c)  |                  |
| Advice   | Nearside Front Front wheel bearing has slight play (2.5.A.3c) |                  |
| Advice   | Nearside Front Tyre worn close to the legal limit (4.1.E.1)   |                  |

CarCheck.co.uk page 4/13



Fail

KP51CTK

report date: 2024-03-29

 MOT #6
 2009-12-02 14:33

 MOT test number
 303996939331

 Result
 ✓ Passed

 MOT #5
 2009-11-30 13:53

 MOT test number
 174044939339

 Result
 X Failed

 Fail
 Nearside Front Brake pipe excessively corroded (3.6.B.2c)

Offside Front Brake pipe excessively corroded (3.6.B.2c)

MOT test number

Result

Advice Offside Rear brake disc slightly pitted (3.5.1h)

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear brake disc slightly pitted (3.5.1h)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

| MOT #3          | 2007-11-29 15:44 |
|-----------------|------------------|
| MOT test number | 173923437395     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 5/13



report date: 2024-03-29

| MOT #2   |   | 2006-11-06 14:21 |
|----------|---|------------------|
| MOT test | number  | 143610016352     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear brake disc slightly pitted (3.5.1h)              |                  |
| Advice   | Offside Front Front wheel bearing has slight play (2.5.A.3c)  |                  |
| Advice   | Nearside Rear brake disc slightly pitted (3.5.1h)             |                  |
| Advice   | Nearside Front Front wheel bearing has slight play (2.5.A.3c) |                  |

| MOT #1          | 2005-11-14 13:59 |
|-----------------|------------------|
| MOT test number | 951748615341     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 6/13



## Tax & MOT check



**Х** МОТ

Expired: 19 July 2021

| Tax status       | Expired at 25 January 2021 |
|------------------|----------------------------|
| Days left        | 1190 days too late         |
| MOT expiry date  | 19 July 2021               |
| Full MOT history | See MOT history            |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| venicle class                           | 70         |
| Band                                    | K          |
| Single payment (12 months)              | £ 395,00,- |
| Single six month payment                | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |

CarCheck.co.uk page 7/13



report date: 2024-03-29

## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Туре     |  |

#### Damage 2

| Dalliage 2 |  |
|------------|--|
| Date       |  |
| Category   |  |





#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



| Owner history   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlondere. |             |
| ***************************************   |             |
| ***************************************   |             |
| ***************************************   |             |
| ***************************************   |             |
| ***************************************   |             |
| ***************************************   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this MERCEDES had different number plates.   |             |
| Number of plates  |             |
| Current registration  | NK SIN      |
| Plate since   |             |
| Current registration  | NK WE       |
| Plate since   |             |
|   | More info > |
|   |             |

CarCheck.co.uk page 10/13



## Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 18         |
| First mileage registration | 2001-10-22 |
| Last registration          | 2020-07-20 |
| Complete history           | See info   |



| Registration #1  | 2001-10-22 | 7 mi       |
|------------------|------------|------------|
| Registration #2  | 2005-11-14 | 28.375 mi  |
| Registration #3  | 2006-11-06 | 34.353 mi  |
| Registration #4  | 2007-11-29 | 39.499 mi  |
| Registration #5  | 2008-11-28 | 43.782 mi  |
| Registration #6  | 2009-11-30 | 48.273 mi  |
| Registration #7  | 2009-12-02 | 48.289 mi  |
| Registration #8  | 2011-01-19 | 54.621 mi  |
| Registration #9  | 2012-02-24 | 55.981 mi  |
| Registration #10 |            | 71.777 es  |
| Registration #11 |            | 11.777 es  |
| Registration #12 |            | 11.777 es  |
| Registration #13 |            | 11.777 es  |
| Registration #14 |            | 11.777 es  |
| Registration #15 |            | 91,700 esi |
| Registration #16 |            | 11.777 es  |
| Registration #17 |            | 11.777 es  |
| Registration #18 |            | 11.177 es  |

More info >

CarCheck.co.uk page 12/13



# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width       | 1722 mm |
|-------------|---------|
| Height      | 1345 mm |
| Length      | 4567 mm |
| Wheel base  | 2690 mm |
| Kerb weight | 1420 kg |

# Additional information

| Fuel tank capacity | 62 I                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 2                     |
| Number of axles    | 2                     |
| Engine number      | 11294031081277        |

CarCheck.co.uk page 13/13