



PEUGEOT



report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | PEUGEOT |
| Model | 108 ALLURE TOP |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 99 mph |
| 0 - 60 mph | 15.9 seconds |
| Gearbox | 5 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 68 BHP |
| Max. torque | 95 Nm at 4.300 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 56.5 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 97 g/km |
| CO2 label | A |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-03 |
| Pictures | 10 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-25 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 18 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #8 | 2024-03-19 15:07 |
| MOT test number | 550626689977 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-25 |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|---|
| MOT #7 | 2024-03-19 10:50 |
| MOT test number | 394675691392 |
| Result | ✗ Failed |
| MAJOR | Oil leaking excessively from engine sump (8.4.1 (a) (i)) |
| MAJOR | Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| DANGEROUS | Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2.0mm remain (5.2.3 (e)) |
| MAJOR | Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| MAJOR | Parking brake efficiency below requirements (1.4.2 (a) (i)) |
| DANGEROUS | Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |

**MOT #6** 2023-03-22 10:30**MOT test number** 868710009573**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2022-03-26 13:33**MOT test number** 685959876681**Result** ✓ Passed**MOT #4** 2021-05-01 10:24**MOT test number** 692071905403**Result** ✓ Passed**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #3** 2021-05-01 10:24**MOT test number** 616932252958**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen washer not working (3.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Offside Front Windscreen washer not working (3.5 (a))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))



| | |
|------------------------|---------------------------------|
| MOT #2 | 2020-05-02 08:37 |
| MOT test number | 921181237640 |
| Result | ✓ Passed |
| Advice | Nearside Outer sill is damaged. |

| | |
|------------------------|----------------------------|
| MOT #1 | 2020-04-21 12:18 |
| MOT test number | 421091376568 |
| Result | ✓ Passed |
| Advice | COVID-19 6 MONTH EXTENSION |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
25 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 25 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | E |
| First licence fee (12 months) | £ 165,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2017-04-30 |
| Last registration | 2024-03-19 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2017-04-30 | 15 mi |
| Registration #2 | 2020-05-02 | 18.450 mi |
| Registration #3 | 2020-05-02 | 20.277 mi |
| Registration #4 | 2021-05-01 | 25.460 mi |
| Registration #5 | 2021-05-01 | 25.460 mi |
| Registration #6 | 2020-05-02 | 20.277 mi |
| Registration #7 | 2020-05-02 | 20.277 mi |
| Registration #8 | 2020-05-02 | 20.277 mi |
| Registration #9 | 2020-05-02 | 20.277 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1884 mm |
| Height | 1460 mm |
| Length | 3475 mm |
| Wheel base | 2340 mm |
| Kerb weight | 860 kg |
| Max. allowed weight | 1240 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Engine number | 8372885 |