



HONDA

AVIIYSG

report date: 2024-03-28

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Blue
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-11-19
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-18
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	3

MOT #14	2023-12-15 11:04
MOT test number	118342716063
Result	✓ Passed
Next expiry date	2024-12-18
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated perished (5.3.4 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Worn very close to limit (5.2.3 (e))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated perished (5.3.4 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Cracking and worn close to limit (5.2.3 (d) (ii))
Minor	Offside Rear Position lamp light intensity obviously reduced condensated and damp (4.2.3 (a) (i))

**MOT #13** 2023-12-12 16:54**MOT test number** 563097354554**Result** ✗ Failed**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn very close to limit (5.2.3 (e))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated perished (5.3.4 (b) (i))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Offside Rear Position lamp light intensity obviously reduced condensated and damp (4.2.3 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking and worn close to limit (5.2.3 (d) (ii))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated perished (5.3.4 (b) (i))**MOT #12** 2022-12-19 10:34**MOT test number** 456544855291**Result** ✓ Passed**MOT #11** 2021-07-08 08:23**MOT test number** 401105250088**Result** ✓ Passed**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MOT #10** 2020-06-22 11:58**MOT test number** 108889443399**Result** ✓ Passed**MOT #9** 2019-07-05 15:27**MOT test number** 634603057132**Result** ✓ Passed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2018-08-25 10:40**MOT test number** 553489112314**Result** ✓ Passed**MOT #7** 2017-08-26 09:23**MOT test number** 329251629188**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #6 2016-09-09 12:23**MOT test number** 390100983290**Result** ✓ Passed**MOT #5** 2016-09-08 08:19**MOT test number** 417418725894**Result** ✗ Failed

- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

MOT #4 2015-10-09 09:23**MOT test number** 186265319519**Result** ✓ Passed**MOT #3** 2015-10-09 09:23**MOT test number** 866995453445**Result** ✗ Failed

- Pass with rectification** Nearside Rear rear brake binding (3.7.B.1)



MOT #2	2014-10-17 16:40
MOT test number	478540794240
Result	✓ Passed

MOT #1	2014-07-16 12:22
MOT test number	798697394141
Result	✓ Passed

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
18 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	18 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-07-29
Last registration	2023-12-15
Complete history	See info



Registration #1	2011-07-29	13 mi
Registration #2	2014-07-16	33.755 mi
Registration #3	2014-10-17	35.818 mi
Registration #4	2015-10-09	43.711 mi
Registration #5	2015-10-09	43.711 mi
Registration #6	2016-09-08	52.233 mi
Registration #7	2016-09-09	52.233 mi
Registration #8	2017-08-26	74.238 mi
Registration #9	2019-05-29	95.277 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2019-05-29	95.277 mi
Registration #14	2019-05-29	95.277 mi
Registration #15	2019-05-29	95.277 mi
Registration #16	2019-05-29	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1004814