



General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-06-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-04-14
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	30
Total items failed	18

MOT #17	2022-03-26 09:22
MOT test number	400041477726
Result	✓ Passed
Next expiry date	2023-04-14
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-04-15 08:50
MOT test number	791728754439
Result	✓ Passed

MOT #15	2021-04-14 12:49
MOT test number	844165824170
Result	✗ Failed
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Exhaust system insecure (6.1.2 (a))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #14** 2020-01-21 16:05**MOT test number** 722103605655**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2020-01-21 11:20**MOT test number** 242287706714**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**MOT #12** 2019-01-17 09:42**MOT test number** 978132342740**Result** ✓ Passed**Advice** Rear exhaust mounting broken, still secure**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2019-01-05 14:05

MOT test number

364551275341

Result**✗ Failed**

- Advice** Rear exhaust mounting broken, still secure
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10

2018-01-23 14:24

MOT test number

420868728016

Result**✓ Passed**

- Advice** E.m.l on
- Advice** Exhaust corroded on inside
- Advice** Emissions high co

MOT #9

2018-01-23 09:51

MOT test number

211813871992

Result**✗ Failed**

- Advice** Emissions high co
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** E.m.l on
- Advice** Exhaust corroded on inside

**MOT #8**

2017-01-26 12:32

MOT test number

331902763712

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Both front tyres worn on inner edges
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #7

2017-01-26 09:57

MOT test number

963284986579

Result

✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Both front tyres worn on inner edges
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6

2016-01-26 09:53

MOT test number

428180191374

Result

✓ Passed

- Advice** Both rear tyres worn on edges 205/55r16

**MOT #5** 2015-03-30 17:24**MOT test number** 867149285031**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-03-30 17:24**MOT test number** 935359285076**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #3** 2014-02-14 10:49**MOT test number** 186325444427**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** O/s/r tyre perished**MOT #2** 2013-02-20 15:52**MOT test number** 227361253096**Result** ✓ Passed**MOT #1** 2013-02-20 09:53**MOT test number** 716141153087**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	MA10YBS
Plate since	2019-03-28
Current registration	MA10YBS
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-16
Last registration	2022-03-26
Complete history	See info



Registration #1	2010-04-16	8 mi
Registration #2	2013-02-20	26.254 mi
Registration #3	2013-02-20	26.267 mi
Registration #4	2014-02-14	40.833 mi
Registration #5	2015-03-30	61.306 mi
Registration #6	2016-01-26	78.458 mi
Registration #7	2017-01-26	99.721 mi
Registration #8	2017-01-26	99.721 mi
Registration #9	2018-01-23	118.649 mi
Registration #10	2018-01-23	118.649 mi
Registration #11	2019-01-23	118.649 mi
Registration #12	2019-01-23	118.649 mi
Registration #13	2019-01-23	118.649 mi
Registration #14	2019-01-23	118.649 mi
Registration #15	2019-01-23	118.649 mi
Registration #16	2019-01-23	118.649 mi
Registration #17	2019-01-23	118.649 mi
Registration #18	2019-01-23	118.649 mi
Registration #19	2019-01-23	118.649 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AY19587