





report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC 16V
Colour	Silver
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	170 Nm at 4.500 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.2 mpg
CO2 emission	182 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 1

Date 2021-06-06

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-05-24
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	22
Total items failed	2

MOT #19		2023-05-18 17:14
MOT test	number	526524015583
Result		✓ Passed
Next expi	ry date	2024-05-24
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #18		2023-05-18 14:03
MOT test	number	944437996812
Result		× Failed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1	.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
MAJOR	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))	
MAJOR	Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #17 2022-05-25 14:02

MOT test number 976877323121

Result ✓ Passed

MOT #16 2022-05-25 14:02

MOT test number 473145756880

Result X Failed

Pass with rectification
Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #15 2021-05-19 14:42

MOT test number 608532698887

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2020-05-18 12:54

MOT test number 472766887788

MOT #13 2019-03-27 11:26

MOT test number 367246029625

Result
✓ Passed

MOT #12 2018-03-19 10:21

MOT test number 391578570045

Advice Rear number plate starting to de laminate.

Advice N\s\f wheel rim inner damaged.

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #11

MOT test number

983465700101

Result

Advice O\s\r tyre tread low.

Advice Both front tyres worn on inner edges .

 MOT #10
 2016-03-16 11:28

 MOT test number
 609508252504

 Result
 ✓ Passed

 MOT #9
 2016-03-16 10:37

 MOT test number
 666631691772

 Result
 X Failed

 Fail
 Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #8

MOT test number

Result

Notice N\s\r wheel rim slight damage

MOT test number 426821174018

Result Passed

Advice Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #6
 2013-03-14 10:36

 MOT test number
 405373173009

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #5	2012-03-21 10:51
MOT test number	199801082459
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #4		2011-03-22 10:01
MOT test	number	938761581053
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2010-03-24 10:27
MOT test number	370783780014
Result	✓ Passed
MOT #2	2009-03-26 11:04
MOT test number	824075089089
Result	✓ Passed
MOT #1	2008-04-03 12:08
MOT test number	951594898048
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



CE05UEB report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

CE05UEB

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FORD had different number plates. about of pliates

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-30
Last registration	2023-05-18
Complete history	See info



Registration #1	2005-03-30	17 mi
Registration #2	2008-04-03	23.281 mi
Registration #3	2009-03-26	27.337 mi
Registration #4	2010-03-24	32.681 mi
Registration #5	2011-03-22	37.325 mi
Registration #6	2012-03-21	42.339 mi
Registration #7	2013-03-14	46.556 mi
Registration #8	2014-03-12	50.960 mi
Registration #9	2015-03-25	55.460 mi
Registration #10	2016-03-16	57.837 mi
Registration #11	2016-03-16	57.837 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 66

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1931 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Kerb weight	1388 kg
Max. allowed weight	1910 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13