



report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Grey
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	5.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	296 BHP
Max. torque	358 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.9 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	M






Internet history

Entry 1

Date	2022-01-26
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-21
MOT pass rate	100 %
MOT passed	14
Failed MOT tests	0
Total advice items	30
Total items failed	0

## MOT #14 2024-01-09 15:05

MOT test number 215013468747

Result ✓ Passed

Next expiry date 2025-01-21

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material From flexi to caliper.  
(1.1.11 (c))

**Advice** Headlamp washers inoperative.

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material From flexi to caliper.  
(1.1.11 (c))

## MOT #13 2023-01-05 14:42

MOT test number 416175211866

Result ✓ Passed

**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #12** 2022-01-15 15:35**MOT test number** 824871655327**Result** ✓ Passed**MOT #11** 2021-01-22 10:38**MOT test number** 208497210801**Result** ✓ Passed**MOT #10** 2020-08-24 14:53**MOT test number** 757082957750**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9** 2019-09-17 12:19**MOT test number** 280924544608**Result** ✓ Passed**MOT #8** 2018-09-12 08:32**MOT test number** 135573262998**Result** ✓ Passed**MOT #7** 2017-09-11 11:19**MOT test number** 995348543440**Result** ✓ Passed

**MOT #6** 2016-09-08 08:26**MOT test number** 363728158151**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2015-09-15 08:29**MOT test number** 815106729393**Result** ✓ Passed**MOT #4** 2015-03-06 14:43**MOT test number** 129965365468**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

**MOT #3** 2014-03-07 13:30**MOT test number** 557476764058**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2013-03-05 13:09
MOT test number	425074063076
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-03-07 09:40
MOT test number	156457662071
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
21 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	21 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-11
Last registration	2024-01-09
Complete history	<a href="#">See info</a>



Registration #1	2009-03-11	18 mi
Registration #2	2012-03-07	6.588 mi
Registration #3	2013-03-05	8.669 mi
Registration #4	2014-03-07	10.986 mi
Registration #5	2015-03-06	13.326 mi
Registration #6	2015-09-15	13.599 mi
Registration #7	2016-09-08	22.923 mi
Registration #8	2017-09-11	26.574 mi
Registration #9	2018-09-11	26.574 mi
Registration #10	2019-09-11	26.574 mi
Registration #11	2020-09-11	26.574 mi
Registration #12	2021-09-11	26.574 mi
Registration #13	2022-09-11	26.574 mi
Registration #14	2023-09-11	26.574 mi
Registration #15	2024-01-09	26.574 mi
Registration #16	2024-01-09	26.574 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1325 mm
Length	4315 mm
Wheel base	2650 mm
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	VQ35-607799