





report date: 2024-03-29

# General information

| Make                | BMW                             |
|---------------------|---------------------------------|
| Model               | 1 SERIES 320I EFFICIENTDYNAMICS |
| Colour              | White                           |
| Year of manufacture | 2013                            |
| Top speed           | 143 mph                         |
| 0 - 60 mph          | 7.6 seconds                     |
| Gearbox             | 8 speed automatic               |

# Engine & fuel consumption

| Power                   | 168 BHP             |
|-------------------------|---------------------|
| Max. torque             | 250 Nm at 1.500 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 38.7 mpg            |
| Consumption extra urban | 65.7 mpg            |
| Consumption combined    | 52.3 mpg            |
| CO2 emission            | 127 g/km            |
| CO2 label               | D                   |



CarCheck.co.uk page 1/12



# Internet history

# Entry 2


Date 2021-07-26


Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

| Date          | 2021-06-14  |
|---------------|-------------|
| Pictures      | 0           |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date    | 2024-04-27 |
|--------------------|------------|
| MOT pass rate      | 89 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 1          |
| Total advice items | 12         |
| Total items failed | 6          |

| MOT #9  | 2023-04-26 12:04 |
|---|------------------|
| MOT test number   | 740715285872     |
| Result  | ✓ Passed         |
| Next expiry date  | 2024-04-27       |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |

| MOT #8  | 2022-04-06 14:06 |
|---|------------------|
| MOT test number   | 365487478305     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #7  | 2021-04-28 09:58 |
| MOT test number   | 607197173047     |
| Result  | <b>✓</b> Passed  |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |

| MOT #6   | 2020-03-04 12:3   | 0 |
|----------|---|---|
| MOT test | <b>number</b> 56783268372   | 5 |
| Result   | ✓ Passe   | d |
| Advice   | Oil leak, but not excessive Diff (8.4.1 (a) (i))  |   |
| Advice   | Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |   |

CarCheck.co.uk page 3/12



Advice

Advice

**AK13FME** 

report date: 2024-03-29

**MOT #5** 2019-02-16 14:08 **MOT** test number 669273110328 ✓ Passed Result **MOT #4** 2018-02-22 17:22 **MOT test number** 150745454287 ✓ Passed Result **MOT #3** 2018-02-22 09:21 **MOT** test number 495140045107 Result × Failed **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Nearside Headlamp aim not tested (1.8.A.1c) Front front brake application uneven (3.7.B.2) Fail Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Windscreen washer provides insufficient washer liquid (8.2.3) Rear rear brake excessively fluctuating Both sides (3.7.B.3) Fail Fail Nearside Headlamp not working on dipped beam (1.7.5a)

| MOT #2   | 2017-04-26 17:03 |
|--|------------------|
| MOT test number                                | 274217695111     |
| Result   | ✓ Passed         |
| Advice Rear Brake pad(s) wearing thin (3.5.1g) |                  |

Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)

Offside Front Outer Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



**MOT #1** 2016-04-25 10:54

**MOT test number** 818441931513

**Result** ✓ Passed

**Advice** Rear

Rear Tyre worn close to the legal limit both (4.1.E.1)

**Advice** 

Front Tyre worn close to the legal limit both (4.1.E.1)

CarCheck.co.uk page 5/12



# Tax & MOT check



| Tax status       | Valid until 1 July |
|------------------|--------------------|
| Days left        | 63                 |
| MOT expiry date  | 27 April 2024      |
| Full MOT history | See MOT history    |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 6/12



**AK13FME** 

report date: 2024-03-29

## Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



## Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e mier metery  |             |
|--|-------------|
| For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report  |             |
|  |             |
| manage of the same |             |
|  |             |
| ***************************************  |             |
|  |             |
| ***************************************  |             |
|  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this BMW had different number plates.   |             |
| Number of plates   | ,           |
| Current registration   | NK NK       |
| Plate since  |             |
| Current registration   | UK NE       |
| Plate since  |             |
|  | More info > |
|  |             |

CarCheck.co.uk page 9/12



## Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info


 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 12         |
| First mileage registration | 2013-04-30 |
| Last registration          | 2023-04-26 |
| Complete history           | See info   |



| Registration #1  | 2013-04-30 | 8 mi      |
|------------------|------------|-----------|
| Registration #2  | 2016-04-25 | 29.376 mi |
| Registration #3  | 2017-04-26 | 49.532 mi |
| Registration #4  | 2018-02-22 | 62.145 mi |
| Registration #5  | 2018-02-22 | 62.156 mi |
| Registration #6  | 2019-02-16 | 76.383 mi |
| Registration #7  |            | 11.777 es |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 9.777 es  |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | n.m.      |

More info >

CarCheck.co.uk page 11/12



# Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| 50501 |                  |
| S0566 |                  |
| S0567 |                  |
| 50569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 95%             |
| Children       | 84%             |
| Pedestrian     | 78%             |
| Safety systems | 86%             |
| Overall rating | 89%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1811 mm |
|---------------------|---------|
| Height              | 1428 mm |
| Length              | 4624 mm |
| Wheel base          | 2810 mm |
| Kerb weight         | 1410 kg |
| Max. allowed weight | 1960 kg |

# Additional information

| Fuel tank capacity                | 60 I             |       |
|-----------------------------------|------------------|-------|
| Fuel delivery                     | Direct Injection |       |
| Number of doors                   | 4                |       |
| Number of seats<br>CarCheck.co.uk | 5 page           | 12/12 |

Number of axles 2

**Engine number** A678J579