





report date: 2024-03-28

## General information

Make	CITROEN	
Model	BERLINGO 625 LX L1 BLUEHDI ETG6	
Colour	White	
Year of manufacture	2018	
Top speed	104 mph	
0 - 60 mph	14.8 seconds	
Gearbox	6 speed Semi-Automatic	

## Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-07-01

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-07-06
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	6

MOT #4	2023-07-05 14:31
MOT test number	510833760298
Result	✓ Passed
Next expiry date	2024-07-06
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2022-07-07 13:56
MOT test i	number	103488531711
Result		✓ Passed
Minor	Front Anti-roll bar linkage ball joint dust cover severely deteriorated both	n sides (5.3.4 (b) (i))

MOT #2		2021-05-25 09:15
MOT test	number	346138496956
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on 2.5mm + screw in	tread (5.2.3 (e))
Advice	Nearside front tyre wearing on outer edge	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice	Both front wiper blades smearing	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-05-24 12:00

**MOT test number** 256307739091

**Result** X Failed

**Advice** Nearside front tyre wearing on outer edge

**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

**Advice** Both front wiper blades smearing

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Headlamp aim too high wont adjust (4.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge on 2.5mm + screw in tread (5.2.3 (e))

Fail Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	6 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



LC18UBB report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



factor scincore

LC18UBB

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this CITROEN had different number plates. about of pliates

CarCheck.co.uk page 8/11



LC18UBB report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-05-23
Last registration	2023-07-05
Complete history	See info



Registration #1	2018-05-23	15 mi
Registration #2	2021-05-24	29.456 mi
Registration #3	2021-05-25	29.456 mi
Registration #4		71.777 66
Registration #5		9.77 66
Registration #6		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

## Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1333 kg
Max. allowed weight	1980 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHW3013268

CarCheck.co.uk page 11/11