



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	ACCENT GSI
Colour	Yellow
Year of manufacture	2001
Top speed	101 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	84 BHP
Max. torque	114 Nm at 3.000 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.7 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-02-24
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-03-25
MOT pass rate	80 %
MOT passed	20
Failed MOT tests	5
Total advice items	67
Total items failed	11

MOT #25	2024-03-26 14:21
MOT test number	316919128893
Result	✓ Passed
Next expiry date	2025-03-25

MOT #24	2023-03-09 13:32
MOT test number	155547887112
Result	✓ Passed

MOT #23	2023-03-09 12:57
MOT test number	455551516269
Result	✗ Failed

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #22	2022-02-26 10:31
MOT test number	538483937628
Result	✓ Passed

MOT #21	2021-03-17 14:48
MOT test number	498972321687
Result	✓ Passed

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #20**

2020-03-21 08:40

**MOT test number**

709910580764

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Outer Prop shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19**

2020-03-14 10:57

**MOT test number**

173740499563

**Result**

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Outer Prop shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #18**

2019-03-26 16:13

**MOT test number**

333959535100

**Result**

✓ Passed

**MOT #17** 2018-06-25 14:19**MOT test number** 239423941698**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin all (1.1.13 (a) (ii))**MOT #16** 2018-06-25 11:42**MOT test number** 767557616970**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin all (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #15** 2017-07-06 15:45**MOT test number** 185619002608**Result** ✓ Passed**MOT #14** 2017-07-06 15:45**MOT test number** 310152779328**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)



MOT #13

2016-06-27 12:49

MOT test number

894382537546

Result

✓ Passed

- Advice

Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt outer (2.5.C.1a)
- Advice

Nearside Rear tyre cracks
- Advice

Nearside Front tyre cracks
- Advice

Nearside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)
- Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Nearside number plate lamp appears dim
- Advice

Oil leak
- Advice

Nearside Rear wheel bearing slightly rough when rotated
- Advice

Offside Rear tyre cracks
- Advice

Check engine lamp on
- Advice

Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Offside number plate lamp appears dim



MOT #12

2016-06-27 12:49

MOT test number

373502307402

Result

✗ Failed

Pass with rectification

Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)

Advice

Nearside Rear tyre cracks

Advice

Nearside Front tyre cracks

Advice

Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Nearside number plate lamp appears dim

Pass with rectification

Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)

Advice

Nearside Rear wheel bearing slightly rough when rotated

Advice

Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt outer (2.5.C.1a)

Advice

Offside Rear tyre cracks

Advice

Nearside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)

Advice

Check engine lamp on

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Oil leak

Advice

Offside number plate lamp appears dim

**MOT #11**

2015-06-11 16:29

**MOT test number**

456932565140

**Result**

✓ Passed

- Advice** Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)
- Notice** Cracks to nearside rear tyre
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)
- Notice** Check engine lamp on
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Cracks to offside rear tyre
- Notice** Nearside rear wheel bearing slightly rough when rotated
- Notice** Oil leak

**MOT #10**

2014-06-12 12:23

**MOT test number**

756113164196

**Result**

✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Engine mil lamp on
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



**MOT #9** 2013-07-03 12:04**MOT test number** 286424583457**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)

**MOT #8** 2012-06-29 12:06**MOT test number** 119281782100**Result** ✓ Passed

- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)
- Notice** E.M.L ON
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

**MOT #7** 2011-07-08 09:35**MOT test number** 576029381171**Result** ✓ Passed

- Advice** Nearside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)
- Notice** EML on
- Notice** Slight deterioration front and rear number plates
- Advice** Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)
- Notice** Drivers floor mat insecure

**MOT #6** 2010-06-24 13:32**MOT test number** 702205470177**Result** ✓ Passed

**MOT #5** 2009-07-02 12:56**MOT test number** 271043289419**Result** ✓ Passed**Notice** Front brake pads 60% worn**MOT #4** 2008-07-14 14:10**MOT test number** 202316798178**Result** ✓ Passed**Notice** O/s/f + n/s/f tyre down to 3mm**MOT #3** 2008-07-14 13:26**MOT test number** 200907998497**Result** ✓ Passed**Notice** N/s/f + o/s/f tyre down to 3mm**MOT #2** 2007-07-30 13:16**MOT test number** 342651117262**Result** ✓ Passed**MOT #1** 2006-07-28 09:42**MOT test number** 992499906254**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
25 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	25 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>Y445BLJ</b>
Plate since	2023-03-29
Current registration	<b>Y445BLJ</b>
Plate since	2023-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2001-08-04
Last registration	2024-03-26
Complete history	<a href="#">See info</a>



Registration #1	2001-08-04	24 mi
Registration #2	2006-07-28	13.173 mi
Registration #3	2007-07-30	15.064 mi
Registration #4	2008-07-14	17.846 mi
Registration #5	2008-07-14	17.846 mi
Registration #6	2009-07-02	20.072 mi
Registration #7	2010-06-24	21.685 mi
Registration #8	2011-07-08	23.012 mi
Registration #9	2012-06-29	24.245 mi
Registration #10	2013-07-03	25.431 mi
Registration #11	2014-06-12	26.374 mi
Registration #12	2015-06-11	27.489 mi
Registration #13	2016-06-27	28.634 mi
Registration #14	2016-06-27	28.634 mi
Registration #15	2016-06-27	28.634 mi
Registration #16	2016-06-27	28.634 mi
Registration #17	2016-06-27	28.634 mi
Registration #18	2016-06-27	28.634 mi
Registration #19	2016-06-27	28.634 mi
Registration #20	2016-06-27	28.634 mi
Registration #21	2016-06-27	28.634 mi
Registration #22	2016-06-27	28.634 mi
Registration #23	2016-06-27	28.634 mi
Registration #24	2016-06-27	28.634 mi
Registration #25	2016-06-27	28.634 mi
Registration #26	2016-06-27	28.634 mi



More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1803 mm
Height	1397 mm
Length	4114 mm
Wheel base	2400 mm
Kerb weight	935 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4EAY973583